



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



#### **2020 MITSUBISHI PAJERO**

## GLS HIGHLINE SIGNATURE EDITION | 47,577 KM

VIN: JE4NR62R6LJ711300

# **Car highlights**



## **Low Mileage**

This car has been driven less than 15,000 km a year



#### **Cruise control**

Cruise control to drive with ease & comfort

## **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



#### **Bluetooth**


Enjoy your drive with bluetooth



## **Amazing Comfort**


Power driver seat

### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Fog Light Front	<b>~</b>	Roof Rails	<b>✓</b>
Running Lights	<b>~</b>	Rear Bumper Spoiler	<b>✓</b>
Halogen Headlights	<b>~</b>	HID Headlights	<b>✓</b>
Safety & Security			
Parking Sensors Rear	•	Reverse Camera	<b>✓</b>
Blind Spot Monitor	<b>~</b>	Traction Control	•
Airbag Curtain Shield	<b>✓</b>	Airbag Driver Front	<b>✓</b>
ABS	<b>✓</b>	Central Locking	<b>✓</b>
Child Safety Locking	<b>✓</b>		
Rear Seat Entertainment	<b>✓</b>	Bluetooth Player	•
USB Charging Port	<b>✓</b>	Infotainment System	•
USB player	<b>✓</b>		

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right A to B Pillar	<b>✓</b>	Left B Pillar	•
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board	<b>✓</b>
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Apron	<b>✓</b>
Boot Floor	<b>✓</b>	Firewall Condition	<b>✓</b>
Cowl Top	<b>✓</b>	Head Light Support Condition	<b>✓</b>
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel cover	<b>✓</b>	Antenna	•
Grill Condition	(!)	Monogram	<b>✓</b>
Light Scuffing < 50mm		Ü	
Window Glass	<b>✓</b>	Wiper	<b>✓</b>
Panel Condition			
Rear Trunk Panel	<b>✓</b>		

<b>Engine &amp; Transmission</b>			
Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Radiator Condition	<b>✓</b>	Radiator Coolant	<b>✓</b>
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Drive Axle	<b>✓</b>
4*4 Condition (If Applicable)	<b>✓</b>	Transmission Fluid	<b>✓</b>
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>
Suspension			
Shock Absorbers	<b>✓</b>		
Electricals, Controls & Lights			
Keys			
Master Key	<b>✓</b>	Spare Key(s)	<b>✓</b>
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		

Controls	<b>✓</b>	Cruise Control	•
Heads Up Display	<b>✓</b>	Infotainment Display	•
OBD Connector	<b>✓</b>	Radar (If Equipped)	<b>✓</b>
Music System	•	Camera	<b>✓</b>
Lights			
Headlight	<b>✓</b>	Interior Lights	<b>✓</b>
Tail Light Cluster	<b>✓</b>	Daylight Running Lights	•
License Plate Light	<b>✓</b>		
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	•
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Heater	<b>✓</b>	Rear Blower Switch	<b>✓</b>
Parking Sensors	<b>✓</b>	USB Charging Port	<b>✓</b>
Rear Entertainment	<b>✓</b>	Power/ Manual Windows	<b>✓</b>
Rear Entertainment  Interiors & Luggage	•	Power/ Manual Windows	<b>~</b>
	<ul><li></li><li></li></ul>	Power/ Manual Windows  Central Console	<b>✓</b>
🖺 Interiors & Luggage	<ul><li></li><li></li><li></li></ul>		<ul><li></li><li></li><li></li></ul>
Interiors & Luggage  Dashboard And Instrument Panel	<ul><li>*</li><li>*</li><li>*</li><li>*</li></ul>	Central Console	
Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder	<ul><li>*</li><li>*</li><li>*</li><li>!</li></ul>	Central Console  Glove Box	
Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel  Seat Upholstery	•	Central Console  Glove Box  Sunvisor	•
Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel  Seat Upholstery  Rear Right Seat: Smudge/Crack		Central Console  Glove Box  Sunvisor  Manual Seat Movement	<ul><li></li><li></li></ul>
Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel  Seat Upholstery Rear Right Seat: Smudge/Crack  Seat Belts		Central Console  Glove Box  Sunvisor  Manual Seat Movement  Head Rest	<ul><li>*</li><li>*</li></ul>
Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel  Seat Upholstery Rear Right Seat: Smudge/Crack  Seat Belts  Door Controls And Trim		Central Console  Glove Box  Sunvisor  Manual Seat Movement  Head Rest  Grab Handle	<ul><li></li><li></li><li></li><li></li><!--</td--></ul>

### Tyres Tyres Condition Left Hand Side Front Tyre Left Hand Side Rear Tyre Right Hand Side Front Tyre Right Hand Side Rear Tyre Spare Tyre Life remaining LHS Front Tyre <85% LHS Rear Tyre <85% RHS Front Tyre <75% RHS Rear Tyre <85% Spare Tyre <65%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE