



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.



2021 NISSAN X TERRA SE | 76,918 KM

VIN: MNTAD3N66M6000278

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Traction Control	✓	Airbag Driver Front	✓
ABS	~	Central Locking	✓
Child Safety Locking	~		
Exteriors			
Roof Rails	~	Running Lights	~
Rear Bumper Spoiler	~	LED Headlights	~
⊈ Entertainment			
Bluetooth Player	~	Infotainment System	~
USB player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	~	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	•
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	~	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	~	Antenna	✓
Grill Condition	(!)	Monogram	✓
Scuffing > 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	~		

Engine & Transmission			
Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		
Steering, Suspension & Brakes			
Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		
Electricals, Controls & Lights			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		

Controls	✓	Cruise Control	✓
Infotainment Display	~	OBD Connector	•
Music System	✓	Camera	✓
Lights			
Headlight	~	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	~	AC Switch	✓
AC System Leaks	~	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Parking Sensors	✓	Rear Defogger	•
USB Charging Port	✓	Power/ Manual Windows	✓
USB Charging Port Interiors & Luggage	•	Power/ Manual Windows	•
		Power/ Manual Windows Central Console	•
🖺 Interiors & Luggage			
Interiors & Luggage Dashboard And Instrument Panel	***	Central Console	 * * *
Interiors & Luggage Dashboard And Instrument Panel Cup Holder	****	Central Console Glove Box	<!--</td-->
Interiors & Luggage Dashboard And Instrument Panel Cup Holder Steering Wheel		Central Console Glove Box Sunvisor	
Interiors & Luggage Dashboard And Instrument Panel Cup Holder Steering Wheel Seat Upholstery		Central Console Glove Box Sunvisor Manual Seat Movement	
Interiors & Luggage Dashboard And Instrument Panel Cup Holder Steering Wheel Seat Upholstery Seat Belts		Central Console Glove Box Sunvisor Manual Seat Movement Head Rest	
Interiors & Luggage Dashboard And Instrument Panel Cup Holder Steering Wheel Seat Upholstery Seat Belts Door Controls And Trim		Central Console Glove Box Sunvisor Manual Seat Movement Head Rest Grab Handle	

Tyres Tyres Condition Left Hand Side Front Tyre Left Hand Side Rear Tyre Right Hand Side Front Tyre Right Hand Side Rear Tyre Spare Tyre Life remaining LHS Front Tyre <65% LHS Rear Tyre <75% RHS Front Tyre <65% RHS Rear Tyre <75% Spare Tyre <65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE