



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 MG ZS

LUXURY TROPHY | 36,250 KM

VIN: LSJW74C91NZ072284

Car highlights



Manufacturer warranty

Till 15/02/2028 or 2,00,000 km (Not verified)



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play
















Enjoy your drive with apple play



Amazing Comfort












Power driver seat





Basic Details

| | | | |
|--|-------------------|---|--------------------|
|  Kilometers | 36250 |  Specs | Yes |
|  Engine | 1.3L |  Option Type | Fully Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Red |
|  Interior Trim | Leather Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 1 Keys |
|  VIN number | LSJW74C91NZ072284 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Safety & Security | | | |
|---|---|-----------------------|---|
| 360 degree Camera |  | Parking Sensors Rear |  |
| Reverse Camera |  | Blind Spot Monitor |  |
| Traction Control |  | Front Camera |  |
| Side Camera |  | Airbag Curtain Shield |  |
| Airbag Driver Front |  | ABS |  |

| | | | |
|--|---|---------------------------------|---|
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Exteriors | | | |
| Fog Light Front | ✓ | Roof Rails | ✓ |
| Running Lights | ✓ | LED Headlights | ✓ |
|  Comfort & Convenience | | | |
| Cruise Control | ✓ | Steering Mounted Audio Controls | ✓ |
| Power Folding Mirrors | ✓ | Rear Defogger | ✓ |
| Central Armrest | ✓ | Automatic Headlights | ✓ |
| Steering Column Adjuster | ✓ | | |
|  Performance | | | |
| Hill Descent Control | ✓ | | |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | USB Charging Port | ✓ |
| Infotainment System | ✓ | USB player | ✓ |

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 


Exterior

Doors condition

| | | | |
|-----------------|---|---|---|
| Front left door |  | Front right door Panel: Light Scuffing < 50mm, Low Visibility Dent < 30mm |  |
|-----------------|---|---|---|

| | | | |
|----------------|---|--|---|
| Rear left door |  | Rear right door Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm |  |
|----------------|---|--|---|

Fenders Condition

| | | | |
|-------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
|-------------|---|--------------|---|


Quarter Panels Condition

| | | | |
|--------------------|---|---------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|---|---------------------|---|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | |
| Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |  |

Hood Condition

| | |
|------|---|
| Hood |  |
|------|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|---------------------------------------|---|------------------------------|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition | ! |
| | | Light Scuffing < 50mm | |
| Monogram | ✓ | Window Glass | ✓ |

| | |
|------------------|---|
| Wiper | ✓ |
| Panel Condition | |
| Rear Trunk Panel | ✓ |

Engine & Transmission

| | | |
|--------------------------------|---|----------------------|
| Engine | | |
| Engine Body | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓ |
| Turbocharger/ Supercharger | ✓ | Radiator Condition ✓ |
| Radiator Coolant | ✓ | |
| Fuel System | | |
| Fuel Tank | ✓ | |
| Transmission Operation | | |
| Gear Shifting | ✓ | Drive Axle ✓ |
| Transmission Fluid | ✓ | |

Steering, Suspension & Brakes

| | | |
|------------------------|---|-------------------------|
| Steering | | |
| Steering wheel | ✓ | |
| Brake System | | |
| Parking Brake | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓ |
| Suspension | | |
| Shock Absorbers | ✓ | |

Electricals, Controls & Lights

| | |
|----------------------|---|
| Keys | |
| Master Key | ✓ |
| Door Locks | |
| Child Safety Locking | ✓ |

| | | | |
|----------------------|---|--|---|
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Music System | ✓ | | |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights Right DRL: Low Brightness | ! |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |
| Seat Heaters | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |

| | | | |
|---|---|----------------------|---|
| Steering Wheel Color Faded | ⚠ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim Front Left Door: Light Scuffing | ⚠ | Grab Handle | ✓ |
| Carpet Front Left Floor Mat: Smudge/Burn/Crack | ⚠ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <65% |
| Spare Tyre | <45% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE