



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 JEEP COMPASS**

**S LIMITED | 96,807 KM**

VIN: 3C4NJDCB8KT805774

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 96807             |  Specs             | Yes                 |
|  Engine           | 2.4L              |  Option Type       | Semi Loaded         |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive    |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 11.2 km/L mileage   |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Blue |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | 3C4NJDCB8KT805774 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |  |                                                                                     |                               |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------|-------------------------------|---------------------------------------------------------------------------------------|
| <div> Safety &amp; Security</div> |  |                                                                                     |                               |                                                                                       |
| Adaptive cruise control                                                                                              |  |  | Lane Departure Warning System |  |
| Navigation                                                                                                           |  |  | Parking Sensors Front         |  |
| Parking Sensors Rear                                                                                                 |  |  | Auto Park Assist              |  |
| Reverse Camera                                                                                                       |  |  | Blind Spot Monitor            |  |
| Collision Warning System                                                                                             |  |  | Traction Control              |  |

|                                                                                                                    |   |                          |   |
|--------------------------------------------------------------------------------------------------------------------|---|--------------------------|---|
| Airbag Curtain Shield                                                                                              | ✓ | Airbag Driver Front      | ✓ |
| ABS                                                                                                                | ✓ | Central Locking          | ✓ |
| Child Safety Locking                                                                                               | ✓ |                          |   |
|  <b>Comfort &amp; Convenience</b> |   |                          |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control           | ✓ |
| Steering Mounted Audio Controls                                                                                    | ✓ | Power Folding Mirrors    | ✓ |
| Power Tailgate/ Power Trunk                                                                                        | ✓ | Rear Defogger            | ✓ |
| Central Armrest                                                                                                    | ✓ | Remote Engine Start      | ✓ |
| Automatic Headlights                                                                                               | ✓ | Steering Column Adjuster | ✓ |
|  <b>Exteriors</b>                 |   |                          |   |
| Fog Light Front                                                                                                    | ✓ | Roof Rails               | ✓ |
| Running Lights                                                                                                     | ✓ | HID Headlights           | ✓ |
|  <b>Performance</b>             |   |                          |   |
| Differential Locks                                                                                                 | ✓ |                          |   |
|  <b>Entertainment</b>           |   |                          |   |
| Bluetooth Player                                                                                                   | ✓ | Apple Play               | ✓ |
| Android Auto Play                                                                                                  | ✓ | USB Charging Port        | ✓ |
| Infotainment System                                                                                                | ✓ | USB player               | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                                                 |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door<br>Panel: Paint Chip-off < 5mm |  |
| Rear left door  |  | Rear right door<br>Panel: Light Scuffing < 50mm |  |

### Fenders Condition

|                                          |                                                                                   |              |                                                                                     |
|------------------------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender<br>Condition: Paint Chip-off |  | Right Fender |  |
|------------------------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                    |                                                                                                     |                                                                                      |
|--------------------|------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel<br>Condition: Light Scuffing, Low Visual Dent,<br>Quarter glass beading damaged |  |
|--------------------|------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                                   |                                                                                     |
|---------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm |  |
|---------------------------------------------------|-------------------------------------------------------------------------------------|

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Trunk Condition

|                                                 |                                                                                     |
|-------------------------------------------------|-------------------------------------------------------------------------------------|
| Trunk<br>Door Trim: Scuff/ Disfiguration > 50mm |  |
|-------------------------------------------------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Pillars Condition

|                                       |   |                                          |   |
|---------------------------------------|---|------------------------------------------|---|
| Left A Pillar                         | ✓ | Right A Pillar                           | ✓ |
| Left A to B Pillar Beading            | ✓ | Right A to B Pillar Beading              | ✓ |
| Right A to B Pillar                   | ✓ | Left B Pillar                            | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading               | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar                      | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                            | ✓ |
| Running Board Condition               |   |                                          |   |
| Left Running Board                    | ✓ | Right Running Board                      | ✓ |
| Sunroof Glass Condition (If Equipped) |   |                                          |   |
| Sun Roof Glass                        | ✓ |                                          |   |
| Windshield Condition                  |   |                                          |   |
| Front Windshield                      | ✓ | Rear Windshield                          | ✓ |
| Structural Assessment                 |   |                                          |   |
| Chassis Condition                     | ✓ | Apron                                    | ✓ |
| Boot Floor                            | ✓ | Firewall Condition                       | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition             | ✓ |
| Cowl Top                              |   |                                          |   |
| Cowl Top                              | ✓ |                                          |   |
| Rear View Mirror Condition            |   |                                          |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror                         | ✓ |
| Right Side Mirror                     | ✓ |                                          |   |
| Alloy Wheel/ Rim                      |   |                                          |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim                     | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim                    | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                                          |   |
| Antenna                               | ✓ | Grill Condition<br>Light Scuffing < 50mm | ! |
| Monogram                              | ✓ | Window Glass                             | ✓ |

|                  |   |  |
|------------------|---|--|
| Wiper            | ✓ |  |
| Panel Condition  |   |  |
| Rear Trunk Panel | ✓ |  |

## Engine & Transmission

|                                |   |                      |
|--------------------------------|---|----------------------|
| Engine                         |   |                      |
| Engine Body                    | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓     |
| Radiator Condition             | ✓ | Radiator Coolant ✓   |
| Fuel System                    |   |                      |
| Fuel Tank                      | ✓ |                      |
| Transmission Operation         |   |                      |
| Gear Shifting                  | ✓ | Drive Axle ✓         |
| 4*4 Condition (If Applicable)  | ✓ | Transmission Fluid ✓ |

## Steering, Suspension & Brakes

|                        |   |                         |
|------------------------|---|-------------------------|
| Steering               |   |                         |
| Steering wheel         | ✓ |                         |
| Brake System           |   |                         |
| Parking Brake          | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓           |
| Suspension             |   |                         |
| Shock Absorbers        | ✓ |                         |

## Electricals, Controls & Lights

|                      |   |                |
|----------------------|---|----------------|
| Keys                 |   |                |
| Master Key           | ✓ | Spare Key(s) ✓ |
| Door Locks           |   |                |
| Child Safety Locking | ✓ |                |
| Dashboard            |   |                |

|                                |   |                                         |   |
|--------------------------------|---|-----------------------------------------|---|
| Instrument Panel               | ✓ |                                         |   |
| Airbags                        |   |                                         |   |
| Airbags                        | ✓ |                                         |   |
| Controls                       | ✓ | Cruise Control                          | ✓ |
| Infotainment Display           | ✓ | OBD Connector                           | ✓ |
| Radar (If Equipped)            | ✓ | Navigation System                       | ✓ |
| Music System                   | ✓ |                                         |   |
| Sunroof Operation              |   |                                         |   |
| Sunroof                        | ✓ |                                         |   |
| Camera                         | ✓ |                                         |   |
| Lights                         |   |                                         |   |
| Headlight                      | ! | Interior Lights                         | ✓ |
| Left: Light Scuff Marks < 50mm |   |                                         |   |
| Tail Light Cluster             | ✓ | Daylight Running Lights                 | ✓ |
| License Plate Light            | ✓ |                                         |   |
| Air Conditioning               |   |                                         |   |
| AC Cooling                     | ✓ | AC Switch                               | ✓ |
| AC System Leaks                | ✓ | Center AC Vent                          | ✓ |
| Front Right AC Vent            | ✓ | Heater                                  | ✓ |
| Rear Blower Switch             | ✓ |                                         |   |
| USB Charging Port              | ✓ | Power/ Manual Windows                   | ! |
|                                |   | Front Left: Master Switch Buttons Faded |   |
| Memory Seats                   | ✓ |                                         |   |

## Interiors & Luggage

|                                |   |                       |   |
|--------------------------------|---|-----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console       | ! |
|                                |   | Arm Rest: Fabric Tear |   |
| Cup Holder                     | ✓ | Glove Box             | ✓ |



|                        |   |                                           |   |
|------------------------|---|-------------------------------------------|---|
| Steering Wheel         | ✓ | Sunvisor                                  | ✓ |
| Seat Upholstery        | ✓ | Manual Seat Movement                      | ✓ |
| Seat Belts             | ✓ | Head Rest                                 | ✓ |
| Door Controls And Trim | ✓ | Grab Handle                               | ✓ |
| Carpet                 | ✓ | Headliner                                 | ✓ |
| Rear View Mirror       | ✓ | Toolkit                                   | ! |
|                        |   | Jack Availability: Toe Hook Not Available |   |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <65% | RHS Rear Tyre             | <75% |
| Spare Tyre                 | <85% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE