



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 MAZDA 6

S | 82,813 KM

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 82813             |  Specs             | Yes                  |
|  Engine           | 2.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 12.8 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 4 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | JM7GL4S30L1411052 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                 |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                  |  |
| Rear Armrest with cupholder                                                                                          |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors                                                                                                |  | Rear Defogger                   |  |
| Central Armrest                                                                                                      |  | Steering Column Adjuster        |  |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                 |                                                                                       |

|                                                                                                        |   |                       |   |
|--------------------------------------------------------------------------------------------------------|---|-----------------------|---|
| Parking Sensors Rear                                                                                   | ✓ | Reverse Camera        | ✓ |
| Traction Control                                                                                       | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front                                                                                    | ✓ | ABS                   | ✓ |
| Central Locking                                                                                        | ✓ | Child Safety Locking  | ✓ |
|  <b>Exteriors</b>     |   |                       |   |
| Running Lights                                                                                         | ✓ | LED Headlights        | ✓ |
|  <b>Entertainment</b> |   |                       |   |
| Bluetooth Player                                                                                       | ✓ | USB player            | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Low Visual Dent



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



|                             |   |                                                         |   |
|-----------------------------|---|---------------------------------------------------------|---|
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading                             | ✓ |
| Right A to B Pillar         | ✓ | Left B Pillar                                           | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading                              | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar                                     | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                                           | ✓ |
| Running Board Condition     |   |                                                         |   |
| Left Running Board          | ✓ | Right Running Board<br>Condition: Light Scuffing < 80mm | ! |
| Windshield Condition        |   |                                                         |   |
| Front Windshield            | ✓ | Rear Windshield                                         | ✓ |
| Structural Assessment       |   |                                                         |   |
| Chassis Condition           | ✓ | Apron                                                   | ✓ |
| Boot Floor                  | ✓ | Firewall Condition                                      | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition                            | ✓ |
| Cowl Top                    |   |                                                         |   |
| Cowl Top                    | ✓ |                                                         |   |
| Rear View Mirror Condition  |   |                                                         |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror                                        | ✓ |
| Right Side Mirror           | ✓ |                                                         |   |
| Alloy Wheel/ Rim            |   |                                                         |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim                                    | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim                                   | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                                                         |   |
| Wheel cover                 | ✓ | Antenna                                                 | ✓ |
| Grill Condition             | ✓ | Monogram                                                | ✓ |
| Window Glass                | ✓ | Wiper                                                   | ✓ |
| Panel Condition             |   |                                                         |   |
| Rear Trunk Panel            | ✓ |                                                         |   |

## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Controls             | ✓ | Cruise Control          | ✓ |
| Infotainment Display | ✓ | OBD Connector           | ✓ |
| Music System         | ✓ | Camera                  | ✓ |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| License Plate Light  | ✓ |                         |   |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC Switch               | ✓ |
| AC System Leaks      | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent  | ✓ | Heater                  | ✓ |
| Rear Blower Switch   | ✓ |                         |   |
| Parking Sensors      | ✓ | Rear Defogger           | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows   | ✓ |

## Interiors & Luggage

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |
| Door Controls And Trim         | ✓ | Grab Handle          | ✓ |
| Carpet                         | ✓ | Headliner            | ✓ |
| Rear View Mirror               | ✓ | Toolkit              | ✓ |

 **Tyres**

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<85%

LHS Rear Tyre

<65%

RHS Front Tyre

<85%

RHS Rear Tyre

<55%

Spare Tyre

<65%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE