



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 RENAULT KOLEOS**

**LE | 79,522 KM**

VIN: VF1HGRND7KC313268

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat, Ventilated Seats

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 79522             |  Specs             | Yes                  |
|  Engine           | 2.5L              |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive     |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 12.0 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number     | VF1HGRND7KC313268 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                 |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                  |  |
| Rear Armrest with cupholder                                                                                          |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors                                                                                                |  | Ventilated Seat                 |  |
| Power Tailgate/ Power Trunk                                                                                          |  | Rear Defogger                   |  |
| Central Armrest                                                                                                      |  | Remote Engine Start             |  |

|                                                                                                                |   |                          |   |
|----------------------------------------------------------------------------------------------------------------|---|--------------------------|---|
| Automatic Headlights                                                                                           | ✓ | Steering Column Adjuster | ✓ |
|  <b>Exteriors</b>             |   |                          |   |
| Fog Light Front                                                                                                | ✓ | Roof Rails               | ✓ |
| Running Lights                                                                                                 | ✓ | Rear Bumper Spoiler      | ✓ |
| LED Headlights                                                                                                 | ✓ |                          |   |
|  <b>Safety &amp; Security</b> |   |                          |   |
| Navigation                                                                                                     | ✓ | Parking Sensors Front    | ✓ |
| Parking Sensors Rear                                                                                           | ✓ | Auto Park Assist         | ✓ |
| Reverse Camera                                                                                                 | ✓ | Blind Spot Monitor       | ✓ |
| Traction Control                                                                                               | ✓ | Airbag Curtain Shield    | ✓ |
| Airbag Driver Front                                                                                            | ✓ | ABS                      | ✓ |
| Central Locking                                                                                                | ✓ | Child Safety Locking     | ✓ |
|  <b>Performance</b>         |   |                          |   |
| Differential Locks                                                                                             | ✓ |                          |   |
|  <b>Entertainment</b>       |   |                          |   |
| Bluetooth Player                                                                                               | ✓ | Apple Play               | ✓ |
| Android Auto Play                                                                                              | ✓ | USB Charging Port        | ✓ |
| Infotainment System                                                                                            | ✓ | USB player               | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door  
Panel: Paint Chip-off < 5mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel  
Condition: Chip, Low Visual Dent



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



|                                       |   |                                              |   |
|---------------------------------------|---|----------------------------------------------|---|
| Left A to B Pillar Beading            | ✓ | Right A to B Pillar Beading                  | ✓ |
| Right A to B Pillar                   | ✓ | Left B Pillar                                | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading                   | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar<br>Light Scuffing < 80mm | ! |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                                | ✓ |
| Running Board Condition               |   |                                              |   |
| Left Running Board                    | ✓ | Right Running Board                          | ✓ |
| Sunroof Glass Condition (If Equipped) |   |                                              |   |
| Sun Roof Glass                        | ✓ |                                              |   |
| Windshield Condition                  |   |                                              |   |
| Front Windshield                      | ✓ | Rear Windshield                              | ✓ |
| Structural Assessment                 |   |                                              |   |
| Chassis Condition                     | ✓ | Apron                                        | ✓ |
| Boot Floor                            | ✓ | Firewall Condition                           | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition                 | ✓ |
| Cowl Top                              |   |                                              |   |
| Cowl Top                              | ✓ |                                              |   |
| Rear View Mirror Condition            |   |                                              |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror                             | ✓ |
| Right Side Mirror                     | ✓ |                                              |   |
| Alloy Wheel/ Rim                      |   |                                              |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim                         | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim                        | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                                              |   |
| Antenna                               | ✓ | Grill Condition                              | ✓ |
| Monogram                              | ✓ | Window Glass                                 | ✓ |
| Wiper                                 | ✓ |                                              |   |

Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Instrument Panel      | ✓ |                         |   |
| Airbags               |   |                         |   |
| Airbags               | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Infotainment Display  | ✓ | OBD Connector           | ✓ |
| Radar (If Equipped)   | ✓ | Navigation System       | ✓ |
| Music System          | ✓ |                         |   |
| Sunroof Operation     |   |                         |   |
| Sunroof               | ✓ |                         |   |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| License Plate Light   | ✓ | Fog Lights              | ✓ |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC Switch               | ✓ |
| AC System Leaks       | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent   | ✓ | Heater                  | ✓ |
| Rear Blower Switch    | ✓ |                         |   |
| Rear Defogger         | ✓ | USB Charging Port       | ✓ |
| Power/ Manual Windows | ✓ | Seat Heaters            | ✓ |



## Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder                     | ✓ | Glove Box       | ✓ |

|                        |   |                                                                 |   |
|------------------------|---|-----------------------------------------------------------------|---|
| Steering Wheel         | ✓ | Sunvisor                                                        | ✓ |
| Seat Upholstery        | ✓ | Manual Seat Movement<br>Driver Seat: Seat Rail Limited Movement | ! |
| Seat Belts             | ✓ | Head Rest                                                       | ✓ |
| Door Controls And Trim | ✓ | Grab Handle                                                     | ✓ |
| Carpet                 | ✓ | Headliner                                                       | ✓ |
| Rear View Mirror       | ✓ | Toolkit                                                         | ✓ |

## Tyres

### Tyres Condition

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <65% | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <65% | RHS Rear Tyre             | <75% |
| Spare Tyre                 | <40% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE