



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 NISSAN KICKS**

**SV | 82,668 KM**

### **Car highlights**



#### **Great Parking Assistance**

Reverse Camera



#### **Navigation**

Navigation to drive with ease & comfort

#### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



#### **Bluetooth**















Enjoy your drive with bluetooth



#### **Amazing Comfort**










Power driver seat



Basic Details

 Kilometers	82668	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	Fuel Efficiency	15.4 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	3N1CP5C97LL487854		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>			
Fog Light Front		Roof Rails	
Halogen Headlights			
<div> Safety &amp; Security</div>			
Navigation		Reverse Camera	
Traction Control		Airbag Driver Front	

ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 <b>Comfort &amp; Convenience</b>			
Steering Mounted Audio Controls	✓	Rear Defogger	✓
Automatic Headlights	✓	Steering Column Adjuster	✓
 <b>Entertainment</b>			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door

Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Low Visual Dent, Chip



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition			
Scuffing > 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓

Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Navigation System	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster			
Right Tail Lamp: Crack / Fair Use Wear < 5mm	!	License Plate Light	✓
Fog Lights			
Left Fog Light: Scuff Marks > 50mm	!		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
USB Charging Port	✓	Power/ Manual Windows	✓

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓





## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<75%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE