



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 MERCEDES BENZ C 200 AMG SPORT PACKAGE | 101,315 KM

VIN: WDDWF4CB1JR382426

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Navigation	~	Parking Sensors Front	~
Parking Sensors Rear	~	Reverse Camera	~
Blind Spot Monitor	~	Traction Control	✓
Airbag Curtain Shield	~	Airbag Knees	✓
Airbag Driver Front	~	ABS	✓
Central Locking	~	Child Safety Locking	~
Performance			
Paddle Shift	~		
Exteriors			
Running Lights	~	LED Headlights	~
୍ୟୁଣ Entertainment			
Bluetooth Player	✓	Infotainment System	✓
USB player			


150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	~
Right C Pillar Trim	✓	Right B to C Pillar	~
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	~		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Face Scuffing	!	Left Rear Alloy/ Rim Rim: Alloy Edge Scuffing	(!)
Right Front Alloy/ Rim	(!)	Right Rear Alloy/ Rim	!
Rim: Alloy Face Scuffing		Rim: Alloy Face/Scuffing	
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	•		
Panel Condition			

Rear Trunk Panel	•		
Engine & Transmission			
Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓
Steering, Suspension & Brakes			
Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		
🛱 Electricals, Controls & Lights			
Keys Master Key			
Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		



Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	•	Seat Belts	•
Head Rest	•	Door Controls And Trim	•
Grab Handle	•	Carpet	•
Headliner	•	Rear View Mirror	•
Toolkit	•		
Tyres			
Tyres Condition			
	✓	Left Hand Side Rear Tyre	✓
Tyres Condition	⋄	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	
Tyres Condition Left Hand Side Front Tyre			✓
Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre	<85%		<85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE