



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 VOLVO XC60**

**B5 ULTIMATE DARK | 103,087 KM**

VIN: YV1L5AUZXN1960306

## Car highlights



### **Great condition**

Car has low imperfections



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Apple play**
















Enjoy your drive with apple play



### **Amazing Comfort**












Power driver seat, Memory Seats

Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 103087            |  Specs             | Yes                  |
|  Engine           | 2.0L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | All Wheel Drive      |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 8 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | YV1L5AUZXN1960306 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                             |   |
|--|---|-----------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                             |   |
| Heads up Display   |  | Cruise Control              |  |
| Memory Seats   |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls  |  | Power Folding Mirrors       |  |
| Power Tailgate/ Power Trunk  |  | Rear Defogger               |  |
| Central Armrest  |  | Automatic Headlights        |  |

|  |   |                          |   |
|--|---|--------------------------|---|
| Steering Column Adjuster   | ✓ |                          |   |
|  <b>Safety &amp; Security</b> |   |                          |   |
| Adaptive cruise control  | ✓ | 360 degree Camera        | ✓ |
| Lane Departure Warning System  | ✓ | Parking Sensors Front    | ✓ |
| Parking Sensors Rear   | ✓ | Reverse Camera           | ✓ |
| Blind Spot Monitor   | ✓ | Collision Warning System | ✓ |
| Traction Control   | ✓ | Front Camera             | ✓ |
| Side Camera  | ✓ | Airbag Curtain Shield    | ✓ |
| Airbag Driver Front  | ✓ | ABS                      | ✓ |
| Central Locking  | ✓ | Child Safety Locking     | ✓ |
|  <b>Exteriors</b>            |   |                          |   |
| Fog Light Front  | ✓ | Roof Rails               | ✓ |
| Running Lights   | ✓ | Rear Bumper Spoiler      | ✓ |
| LED Headlights   | ✓ |                          |   |
|  <b>Entertainment</b>       |   |                          |   |
| Bluetooth Player   | ✓ | Apple Play               | ✓ |
| Android Auto Play  | ✓ | USB Charging Port        | ✓ |
| Infotainment System  | ✓ |                          |   |





# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

|                 |   |                  |   |
|-----------------|---|------------------|---|
| Front left door |  | Front right door |  |
| Rear left door  |  | Rear right door  |  |

Fenders Condition

|                           |   |                              |   |
|---------------------------|---|------------------------------|---|
| Left Fender               |  | Right Fender                 |  |
| Condition: Light Scuffing |   | Right Fender: Light Scuffing |   |


Quarter Panels Condition

|                    |   |                     |   |
|--------------------|---|---------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|---|---------------------|---|

Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

|   |   |
|---|---|
| Rear Bumper                                   |   |
| Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |  |

Hood Condition

|      |   |
|------|---|
| Hood |  |
|------|---|

Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|





Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

|                            |   |                             |   |
|----------------------------|---|-----------------------------|---|
| Left A Pillar              |  | Right A Pillar              |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |

|                                       |   |                              |   |
|---------------------------------------|---|------------------------------|---|
| Right A to B Pillar                   | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                | ✓ |
| Running Board Condition               |   |                              |   |
| Left Running Board                    | ✓ | Right Running Board          | ✓ |
| Sunroof Glass Condition (If Equipped) |   |                              |   |
| Sun Roof Glass                        | ✓ |                              |   |
| Windshield Condition                  |   |                              |   |
| Front Windshield                      | ✓ | Rear Windshield              | ✓ |
| Structural Assessment                 |   |                              |   |
| Chassis Condition                     | ✓ | Apron                        | ✓ |
| Boot Floor                            | ✓ | Firewall Condition           | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                              |   |                              |   |
| Cowl Top                              | ✓ |                              |   |
| Rear View Mirror Condition            |   |                              |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                     | ✓ |                              |   |
| Alloy Wheel/ Rim                      |   |                              |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                              |   |
| Antenna                               | ✓ | Grill Condition              | ✓ |
| Monogram                              | ✓ | Window Glass                 | ✓ |
| Wiper                                 | ✓ |                              |   |
| Panel Condition                       |   |                              |   |

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



|                     |   |                         |   |
|---------------------|---|-------------------------|---|
| Airbags             |   |                         |   |
| Airbags             | ✓ |                         |   |
| Controls            | ✓ | Cruise Control          | ✓ |
| Heads Up Display    | ✓ | Infotainment Display    | ✓ |
| OBD Connector       | ✓ | Radar (If Equipped)     | ✓ |
| Navigation System   | ✓ | Music System            | ✓ |
| Sunroof Operation   |   |                         |   |
| Sunroof             | ✓ |                         |   |
| Lights              |   |                         |   |
| Headlight           | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster  | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ |                         |   |
| Air Conditioning    |   |                         |   |
| AC Cooling          | ✓ | AC Switch               | ✓ |
| AC System Leaks     | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent | ✓ | Heater                  | ✓ |
| Rear Blower Switch  | ✓ |                         |   |
| Parking Sensors     | ✓ | Rear Defogger           | ✓ |
| USB Charging Port   | ✓ | Power/ Manual Windows   | ✓ |
| Memory Seats        | ✓ |                         |   |

---

## Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder                     | ✓ | Glove Box       | ✓ |
| Steering Wheel                 | ✓ | Sunvisor        | ✓ |



|                        |   |                      |   |
|------------------------|---|----------------------|---|
| Seat Upholstery        | ✓ | Manual Seat Movement | ✓ |
| Seat Belts             | ✓ | Head Rest            | ✓ |
| Door Controls And Trim | ✓ | Grab Handle          | ✓ |
| Carpet                 | ✓ | Headliner            | ✓ |
| Rear View Mirror       | ✓ | Toolkit              | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <65% |
| RHS Front Tyre             | <75% | RHS Rear Tyre             | <65% |
| Spare Tyre                 | <55% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE