



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 PEUGEOT 2008

ALLURE | 47,629 KM

VIN: VR3UYNFJ9PJ514987

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play
















Enjoy your drive with apple play



Amazing Comfort











Power driver seat



Basic Details

 Kilometers	47629	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	VR3UYNFJ9PJ514987		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Automatic Headlights		Steering Column Adjuster	
 Safety & Security			
Parking Sensors Rear		Reverse Camera	



















Traction Control	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Exteriors			
Roof Rails	✓	Running Lights	✓
LED Headlights	✓		
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	Infotainment System	✓
USB player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition			
Front left door		Front right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	
Rear left door		Rear right door Panel: Light Scuffing < 50mm	
Fenders Condition			
Left Fender		Right Fender	
Quarter Panels Condition			
Left Quarter Panel		Right Quarter Panel	
Front Bumper Condition			
Front Bumper			
Rear Bumper Condition			
Rear Bumper			
Hood Condition			
Hood			
Trunk Condition			
Trunk			
Trunk conditon			
Trunk			
Roof Condition			
Roof			
Pillars Condition			
Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	

Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Radiator Condition	✓	Radiator Coolant ✓
Fuel System		
Fuel Tank	✓	
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓
Transmission Fluid	✓	

Steering, Suspension & Brakes

Steering		
Steering wheel	✓	
Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Disc & Brake Pad	✓	Brake Fluid ✓
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys		
Master Key	✓	Spare Key(s) ✓
Door Locks		
Child Safety Locking	✓	
Dashboard		
Instrument Panel	✓	
Airbags		
Airbags	✓	
Controls	✓	Cruise Control ✓

Infotainment Display	✓	OBD Connector	✓
Navigation System	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Heater	✓		
USB Charging Port	✓	Power/ Manual Windows	✓



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓



Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Life remaining			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<55%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE