



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 NISSAN X TERRA

PLATINUM | 95,140 KM

VIN: MNTAD3N87M6000260

Car highlights



Manufacturer warranty

Till 31/01/2026 or 10,00,000 km (Not verified)



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play
















Enjoy your drive with apple play



Amazing Comfort












Power driver seat





Basic Details

| | | | |
|--|-------------------|---|---------------------|
|  Kilometers | 95140 |  Specs | Yes |
|  Engine | 2.5L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Four Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Grey |
|  Interior Trim | Leather Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 7 Seats |  Number of keys | 2 Keys |
|  VIN number | MNTAD3N87M6000260 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|-------------------------------|---|
|  Safety & Security | | | |
| 360 degree Camera |  | Lane Departure Warning System |  |
| Navigation |  | Parking Sensors Front |  |
| Parking Sensors Rear |  | Reverse Camera |  |
| Blind Spot Monitor |  | Collision Warning System |  |
| Traction Control |  | Front Camera |  |

| | | | |
|--|---|---------------------------------|---|
| Side Camera | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Comfort & Convenience | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Rear Armrest with cupholder | ✓ | Steering Mounted Audio Controls | ✓ |
| Power Folding Mirrors | ✓ | Rear Defogger | ✓ |
| Central Armrest | ✓ | Remote Engine Start | ✓ |
| Automatic Headlights | ✓ | Steering Column Adjuster | ✓ |
|  Exteriors | | | |
| Fog Light Front | ✓ | Roof Rails | ✓ |
| Running Lights | ✓ | Rear Bumper Spoiler | ✓ |
| LED Headlights | ✓ | | |
|  Entertainment | | | |
| Rear Seat Entertainment | ✓ | Bluetooth Player | ✓ |
| Apple Play | ✓ | Android Auto Play | ✓ |
| USB Charging Port | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |
|  Performance | | | |
| Hill Descent Control | ✓ | Differential Locks | ✓ |

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Low Visibility
Dent < 30mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Light
Scuffing < 50mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Low Visual Dent



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

| | | | |
|-----------------------------|---|------------------------------|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | | Monogram | ✓ |
| Light Scuffing < 50mm | ! | | |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

| | | | |
|-----------------------|---|--|---|
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Radar (If Equipped) | ✓ | Navigation System | ✓ |
| Music System | ✓ | Camera | ✓ |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights Right DRL: Low Brightness | ! |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | Rear Left AC Vent | ✓ |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Rear Entertainment | ✓ |
| Power/ Manual Windows | ✓ | | |



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/
Fair Use Wear



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



| | | | |
|------------------------|---|--------------------------|---|
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ! |
| | | Rear Left: Fair Use Wear | |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| | | | |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <65% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE