



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2017 SUZUKI VITARA

GLX | 115,408 KM

VIN: TSMYD2A23HM253712

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Front, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	115408	 Specs	Yes
 Engine	1.6L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel Efficiency	16.0 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Partial Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	TSMYD2A23HM253712		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Steering Mounted Audio Controls	
Rear Defogger	
Steering Column Adjuster	
 Exteriors	

Fog Light Front		Roof Rails	
Running Lights		Halogen Headlights	
 Performance			
Paddle Shift			
 Safety & Security			
Parking Sensors Front		Parking Sensors Rear	
Traction Control		Airbag Curtain Shield	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Entertainment			
Bluetooth Player		USB player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Weather Strip: Rubber Fair Use Wear

Rear left door



Panel: Scuffing

Front right door



Panel: Light Scuffing < 50mm

Rear right door



Hinge: Door Stopper Fair Use Wear

Fenders Condition

Left Fender



Condition: Low Visual Dent, Scuffing

Right Fender



Right Fender: Light Scuffing, Low Visual Dent

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing

Front Bumper Condition

Front Bumper



Condition: Fair Use Wear

Rear Bumper Condition

Rear Bumper



Rear Bumper: Dent > 50mm, Crack/

Misaligned

Hood Condition

Hood



Bonnet: Light Scuffing < 50mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield		Rear Windshield	✓
Condition: Driver Side/Stone Chip Mark<5mm	!		
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Rear Alloy/ Rim	✓		
Wheel cover	✓	Antenna Bent/Broken/Fair Use Wear/Missing	!
Grill Condition Scuffing > 50mm	!	Monogram	✓
Window Glass	✓	Wiper Rear Wiper Blade: Crack/ Fair Use Wear	!
Panel Condition			

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Cover Fair Use Wear

Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Central Locking Not Working

Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel

Malfunction Indication Lights: Service warning



Light

Airbags		
Airbags	✓	
Controls	✓	Cruise Control
Heads Up Display	✓	Infotainment Display
OBD Connector	✓	Music System Audio Inputs: Not Working
Lights		
Headlight	!	Interior Lights
Left: Low Brightness lamps		✓
Tail Light Cluster	✓	Daylight Running Lights
License Plate Light	!	Fog Lights
Number Plate Lamp Not Working		✓
Air Conditioning		
AC Cooling	✓	AC Switch
AC System Leaks	✓	Center AC Vent
Front Right AC Vent	✓	Heater
Parking Sensors	✓	Rear Defogger
USB Charging Port	✓	Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel		
Dashboard Upholstery: Minor Scuffing/ Disfigurement/ Melted	!	Central Console Box: Minor Crack/Fair Use Wear/ Scuffing
Glove Box	✓	Steering Wheel Steering Wheel Fair Use Wear
Sunvisor	✓	Seat Upholstery Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off
Manual Seat Movement	✓	Seat Belts Rear Center Seat Belt: Buckle Not Functioning Properly

Head Rest		Door Controls And Trim	
Grab Handle		Carpet Front Left Floor Mat: Smudge/Burn/Crack	
Headliner		Rear View Mirror	
Toolkit			

Tyres

Tyres Condition

Left Hand Side Rear Tyre		Right Hand Side Front Tyre	
Right Hand Side Rear Tyre		Spare Tyre	
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE