



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2017 RENAULT DUSTER

PE | 54,667 KM

VIN: VF1HSRCH4HA531807

## Car highlights



### Cruise control

Cruise control to drive with ease & comfort



### Bluetooth

Enjoy your drive with bluetooth

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Amazing Comfort

Power driver seat



### Airbag safety

Airbag Driver Front

## Basic Details

|  |                          |   |                              |
|--|--------------------------|---|------------------------------|
|  Kilometers       | <b>54667</b>             |  Specs             | <b>Yes</b>                   |
|  Engine           | <b>2.0L</b>              |  Option Type       | <b>Basic</b>                 |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>Front Wheel Drive</b>     |
|  Body Type        | <b>SUV</b>               |  Fuel Efficiency   | <b>15.3 km/L mileage</b>     |
|  Wheel Type       | <b>Steel Wheels</b>      |  Exterior Color    | <b>Exterior Color Silver</b> |
|  Interior Trim    | <b>Fabric Trim</b>       |  Number of Airbags | <b>2 Airbags</b>             |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>2 Keys</b>                |
|  VIN number      | <b>VF1HSRCH4HA531807</b> |   |                              |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  <b>Exteriors</b>                 |   |               |   |
|--|---|---------------|---|
| Fog Light Front  |  | Roof Rails    |  |
| Halogen Headlights   |  |               |   |
|  <b>Comfort &amp; Convenience</b> |   |               |   |
| Cruise Control   |  | Rear Defogger |  |
| Steering Column Adjuster   |  |               |   |



## Entertainment

Bluetooth Player



USB player



## Safety & Security

Airbag Driver Front



ABS



Child Safety Locking



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Inner Handle: Color/Chrome Low Brightness

Rear left door



Rear right door



Panel: Colour faded

Panel: Low Visual Dent < 30mm, Light

Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Right Fender: Dent, Light Scuffing

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



|                                  |   |                             |   |
|----------------------------------|---|-----------------------------|---|
| Left A to B Pillar Beading       | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar              | ✓ | Left B Pillar               | ✓ |
| Left B Pillar Trim               | ✓ | Left B to C Pillar Beading  | ✓ |
| Right C Pillar Trim              | ✓ | Right B to C Pillar         | ✓ |
| Right B to C Pillar Beading      | ✓ | Left C Pillar               | ✓ |
| Running Board Condition          |   |                             |   |
| Left Running Board               | ✓ | Right Running Board         | ✓ |
| Windshield Condition             |   |                             |   |
| Front Windshield                 | ✓ | Rear Windshield             | ✓ |
| Structural Assessment            |   |                             |   |
| Chassis Condition                | ✓ | Apron                       | ✓ |
| Boot Floor                       |   |                             |   |
| Condition: Light Scuffing < 80mm | ! | Cowl Top                    | ✓ |
| Head Light Support Condition     | ✓ |                             |   |
| Cowl Top                         |   |                             |   |
| Cowl Top                         | ✓ |                             |   |
| Rear View Mirror Condition       |   |                             |   |
| Left Hand Side Mirror            | ✓ | Left Side Mirror            | ✓ |
| Right Side Mirror                | ✓ |                             |   |
| Alloy Wheel/ Rim                 |   |                             |   |
| Left Front Alloy/ Rim            | ✓ | Left Rear Alloy/ Rim        | ✓ |
| Right Front Alloy/ Rim           | ✓ | Right Rear Alloy/ Rim       | ✓ |
| Spare Alloy/ Rim Condition       | ✓ |                             |   |
| Wheel cover                      | ✓ | Antenna                     | ✓ |
| Grill Condition                  | ✓ | Monogram                    | ✓ |
| Window Glass                     | ✓ | Wiper                       | ✓ |
| Panel Condition                  |   |                             |   |
| Rear Trunk Panel                 | ✓ |                             |   |

## Engine & Transmission

### Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

### Fuel System

Fuel Tank 

### Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

## Steering, Suspension & Brakes

### Steering

Steering wheel 

### Brake System

Brake Master Cylinder  Brake Disc & Brake Pad 

Brake Fluid 

### Suspension

Shock Absorbers 

## Electricals, Controls & Lights

### Keys

Master Key  Spare Key(s) 

### Door Locks

Child Safety Locking 

### Dashboard

Instrument Panel 

### Airbags

Airbags 

|                          |  |  |  |
|--------------------------|--|--|--|
| Controls                 |  | Cruise Control                               |  |
| Heads Up Display         |  | Infotainment Display                         |  |
|                          |  | Infotainment Display: Display Low Brightness |  |
| OBD Connector            |  | Navigation System                            |  |
| Music System             |  | Camera                                       |  |
| <b>Lights</b>            |  |  |  |
| Headlight                |  | Interior Lights                              |  |
| Left: Scuff Marks > 50mm |  |  |  |
| Tail Light Cluster       |  | License Plate Light                          |  |
| <b>Air Conditioning</b>  |  |  |  |
| AC Cooling               |  | AC Switch                                    |  |
| AC System Leaks          |  | Center AC Vent                               |  |
| Front Right AC Vent      |  | Heater                                       |  |
| Fair Use Wear            |  |  |  |
| USB Charging Port        |  | Power/ Manual Windows                        |  |
| Memory Seats             |  |  |  |

## **Interiors & Luggage**

|                                |  |                              |  |
|--------------------------------|--|------------------------------|--|
| Dashboard And Instrument Panel |  | Central Console              |  |
| Glove Box                      |  | Steering Wheel               |  |
|                                |  | Steering Wheel Fair Use Wear |  |
| Sunvisor                       |  | Seat Upholstery              |  |
| Manual Seat Movement           |  | Seat Belts                   |  |
| Head Rest                      |  | Door Controls And Trim       |  |
| Grab Handle                    |  | Carpet                       |  |
| Headliner                      |  | Rear View Mirror             |  |
| Toolkit                        |  |                              |  |

 **Tyres**

## Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



## Life remaining

LHS Front Tyre

&lt;75%

LHS Rear Tyre

&lt;75%

RHS Front Tyre

&lt;75%

RHS Rear Tyre

&lt;75%

Spare Tyre

&lt;55%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE