



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2017 HONDA CIVIC

EXI | 123,203 KM

VIN: 19XFC2676HE450272

Car highlights

Service History

Service history available



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play















Enjoy your drive with apple play



Amazing Comfort











Power driver seat



Basic Details

 Kilometers	123203	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	16.2 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Maroon
 Interior Trim	Fabric Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	19XFC2676HE450272		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Remote Engine Start		Steering Column Adjuster	
 Exteriors			

Fog Light Front	✓	Running Lights	✓
Halogen Headlights	✓		
 Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Side Camera	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	Infotainment System	✓
USB player	✓		





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm	
Rear left door		Rear right door Panel: Colour Mismatch/ Low Brightness, Light Scuffing < 50mm	

Fenders Condition

Left Fender Condition: Light Scuffing		Right Fender Right Fender: Scuffing	
--	---	--	---


Quarter Panels Condition

Left Quarter Panel Condition: Colour faded		Right Quarter Panel	
---	---	---------------------	---


Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	
---	---

Hood Condition

Hood Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm	
---	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar	⚠	Right A Pillar	✓
Condition: Scuffing > 50mm			
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Condition: Passenger Side/Stone Chip	⚠	Rear Windshield	✓
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	⚠	Left Side Mirror	✓
Body: Scuffing, Mirror Casing Fair Use Wear			
Right Side Mirror	⚠		
Body: Light Scuffing			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	⚠	Left Rear Alloy/ Rim	✓
Rim: Alloy Edge Scuffing			
Right Front Alloy/ Rim	⚠	Right Rear Alloy/ Rim	✓
Rim: Alloy Edge Scuffing			
Spare Alloy/ Rim Condition	✓		

Antenna	✓	Grill Condition Light Scuffing < 50mm	⚠
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

🔌 Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓

Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



OBD Connector



Music System



Sunroof Operation

Sunroof



Camera

Reverse Camera: Lens Damaged/ Blurred



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	⚠	Headliner	✓
Front Left Floor Mat: Smudge/Burn/Crack			
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	⚠		
Crack/ Uneven Wear			
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<55%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE