



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 BMW X3

M40I | 33,250 KM

VIN: WBX85DP08NN167821

Car highlights

Service History

Service history available



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat, Memory Seats

Basic Details

 Kilometers	33250	 Specs	Yes
 Engine	3.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WBX85DP08NN167821		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Heads up Display	
Cruise Control	
Rear Armrest with cupholder	
Power Folding Mirrors	
Rear Defogger	
Climate Control AC	
Memory Seats	
Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk	
Central Armrest	

Automatic Headlights		Steering Column Adjuster	
Safety & Security			
Adaptive cruise control		360 degree Camera	
Lane Departure Warning System		Navigation	
Parking Sensors Front		Parking Sensors Rear	
Auto Park Assist		Reverse Camera	
Blind Spot Monitor		Collision Warning System	
Traction Control		Front Camera	
Side Camera		Airbag Curtain Shield	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
Performance			
Paddle Shift		Hill Descent Control	
Exteriors			
Roof Rails		Running Lights	
Rear Bumper Spoiler		LED Headlights	
Entertainment			
Bluetooth Player		Apple Play	
Android Auto Play		USB Charging Port	
Infotainment System		USB player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Light Scuffing < 50mm, Low Visual

Dent < 30mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Bonnet: Light Scuffing < 50mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	
		Rear Right Window Curtain: Fair Use Wear	!
Wiper	✓		
Panel Condition			

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel		
Airbags		
Airbags		
Controls		Cruise Control
Heads Up Display		Infotainment Display
OBD Connector		Radar (If Equipped)
Navigation System		Music System
Sunroof Operation		
Sunroof		
Lights		
Headlight		Interior Lights
Tail Light Cluster		Daylight Running Lights
License Plate Light		
Air Conditioning		
AC Cooling		AC Switch
AC System Leaks		Center AC Vent
Front Right AC Vent		Heater
Rear Blower Switch		Rear Left AC Vent
Parking Sensors		Rear Defogger
USB Charging Port		Power/ Manual Windows
Memory Seats		

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	

Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Life remaining			
LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE