



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2019 DODGE DURANGO**

**GT | 112,512 KM**

VIN: 1C4RDHDG1KC801992

## **Car highlights**

### **Service History**

Service history available



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat, Memory Seats

## Basic Details

 Kilometers	<b>112512</b>	 Specs	<b>Yes</b>
 Engine	<b>3.6L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel Efficiency	<b>8.3 km/L mileage</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>7 Airbags</b>
 Seating Capacity	<b>7 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>1C4RDHDG1KC801992</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Power Tailgate/ Power Trunk		Rear Defogger	
Central Armrest		Remote Engine Start	

Automatic Headlights



Steering Column Adjuster



### Exteriors

Fog Light Front



Running Lights



Rear Bumper Spoiler



Trailer Hook / Coupling



HID Headlights



### Safety & Security

Navigation



Parking Sensors Rear



Reverse Camera



Blind Spot Monitor



Traction Control



Airbag Curtain Shield



Airbag Knees



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



### Performance

Paddle Shift



Hill Descent Control



### Entertainment

Bluetooth Player



Apple Play



Android Auto Play



USB Charging Port



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Light Scuffing < 50mm, Low Visual

Dent < 30mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Beading: Crack/Fair Use Wear<50mm			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Antenna		Grill Condition	
		Light Scuffing < 50mm	
Monogram		Window Glass	

Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel		
Airbags		
Airbags		
Controls		Cruise Control
Infotainment Display		OBD Connector
Radar (If Equipped)		Navigation System
Music System		
Sunroof Operation		
Sunroof		
Camera		
Lights		
Headlight		Interior Lights
Tail Light Cluster		Daylight Running Lights
License Plate Light		Fog Lights
Air Conditioning		
AC Cooling		AC Switch
AC System Leaks		Center AC Vent
Front Right AC Vent		Heater
Rear Blower Switch		Rear Left AC Vent
Rear Defogger		USB Charging Port
Power/ Manual Windows		Seat Heaters
Memory Seats		



## Interiors & Luggage

Dashboard And Instrument Panel		Central Console
--------------------------------	--	-----------------

Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Steering Wheel Fair Use Wear			
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

## Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE