



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2020 KIA PEGAS

LX | 137,740 KM

VIN: LJD0AA298L0122946

Car highlights



Great Parking Assistance

Parking Sensors Rear



Music System

Enjoy your drive with music system

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Amazing Comfort

Power driver seat



Airbag safety

Airbag Driver Front, Airbag Passenger Front

Basic Details

 Kilometers	137740	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel Efficiency	16.6 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LJD0AA298L0122946		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors	
Fog Light Front	
 Safety & Security	
Parking Sensors Rear	
Airbag Passenger Front	
Airbag Driver Front	
ABS	
 Comfort & Convenience	

Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Windows Rear			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front right door



Rear left door



Rear right door



Panel: Low Visual Dent < 30mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Rear Bumper: Fully Repainted

Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Grill Condition			
Fully Repainted			
Panel Condition			
Rear Trunk Panel			

Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Transmission Operation			
Gear Shifting		Drive Axle	

Steering, Suspension & Brakes

Brake System			
Parking Brake		Brake Master Cylinder	
Brake Fluid			
Suspension			
Shock Absorbers			

Electricals, Controls & Lights

Keys			
Master Key			
Dashboard			
Instrument Panel			
Controls		Infotainment Display	
Music System			
Lights			

Headlight



Tail Light Cluster



Air Conditioning



AC Cooling

Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Steering Wheel



Headliner



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<90%

LHS Rear Tyre

<73%

RHS Front Tyre

<90%

RHS Rear Tyre

<73%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE