



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 MITSUBISHI MONTERO SPORT
GLS H/L SIGNATURE EDITION | 61,372 KM**

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	61372	 Specs	Yes
 Engine	3.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MMEMCY1X6NH000450		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Central Armrest	
 Exteriors	

Fog Light Front		Running Lights	
Rear Bumper Spoiler		LED Headlights	

Performance

Paddle Shift		Hill Descent Control	
Differential Locks			

Safety & Security

Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Traction Control	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	

Entertainment

Bluetooth Player		Apple Play	
Android Auto Play		USB Charging Port	
Infotainment System		USB player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Handle: Scuffing

Front right door



Frame: Light Scuffing < 50mm

Rear left door



Rear right door



Frame: Light Scuffing < 50mm

Fenders Condition

Left Fender



Condition: Light Scuffing

Right Fender



Right Fender: Light Scuffing

Quarter Panels Condition

Left Quarter Panel



Trim: Light Scuffing < 80mm

Right Quarter Panel



Condition: Low Visual Dent, Light Scuffing,

Scuffing/ Scratch

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping < 5mm,



Light Scuffing < 50mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof

Roof Moulding Condition: Minor Rubber



Beading Fair Use Wear

Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	

Running Board Condition

Left Running Board		Right Running Board	
		Condition: Light Scuffing < 80mm	

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	--

Windshield Condition

Front Windshield		Rear Windshield	
------------------	--	-----------------	--

Structural Assessment

Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			

Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			

Body: Light Scuffing

Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	

Spare Alloy/ Rim Condition

Antenna		Grill Condition	
		Chrome Fair Use Wear < 30mm	

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking		
Dashboard		
Instrument Panel		
Airbags		
Airbags		
Controls		Cruise Control
Infotainment Display		OBD Connector
Radar (If Equipped)		Music System
Sunroof Operation		
Sunroof		
Lights		
Headlight		Interior Lights
Tail Light Cluster		Daylight Running Lights
License Plate Light		Fog Lights
Air Conditioning		
AC Cooling		AC Switch
AC System Leaks		Center AC Vent
Front Right AC Vent		
Fair Use Wear		Heater
Rear Blower Switch		Rear Left AC Vent
Parking Sensors		Rear Defogger
USB Charging Port		Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel		Central Console
Cup Holder		Glove Box
Steering Wheel		Sunvisor

Seat Upholstery	!	Manual Seat Movement	✓
Driver Seat: Minor Smudge/ Cracks			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<55%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE