



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 TOYOTA C HR

GX | 91,920 KM

VIN: NMTKZ4BX4LR352899

## Car highlights



### Great condition

Car has low imperfections



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>91920</b>	 Specs	<b>Yes</b>
 Engine	<b>1.8L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Hybrid</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>NMTKZ4BX4LR352899</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Steering Mounted Audio Controls	
Central Armrest	
Steering Column Adjuster	
 <b>Safety &amp; Security</b>	

Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			



### Exteriors

Running Lights		Rear Bumper Spoiler	
LED Headlights			



### Entertainment

Bluetooth Player		Apple Play	
Android Auto Play		Infotainment System	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent, Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine		
Engine Body	✓	Engine Performance

Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Fuel System			
Fuel Tank			
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Suspension			
Shock Absorbers			

## Electricals, Controls & Lights

Keys			
Master Key		Spare Key(s)	
Door Locks			
Child Safety Locking			
Dashboard			
Instrument Panel			
Airbags			
Airbags			
Controls			
Cruise Control			
Infotainment Display			
OBD Connector			
Music System			
Camera			

## Lights

Headlight		Interior Lights	
Tail Light Cluster		Daylight Running Lights	
License Plate Light			
<hr/>			
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Parking Sensors		Rear Defogger	
USB Charging Port		Power/ Manual Windows	
Memory Seats			

## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Disfigurement/ Melted		Central Console	
Glove Box		Steering Wheel	
Sunvisor		Seat Upholstery	
Manual Seat Movement		Seat Belts	
Head Rest		Door Controls And Trim	
Grab Handle		Carpet	
		Front Left Floor Mat: Smudge/Burn/Crack	
Headliner		Rear View Mirror	
Toolkit			

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE