



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 PEUGEOT 208

GT LINE | 80,791 KM

VIN: VR3UPHNLXPT001131

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

| | | | |
|--|-----------------------------|---|------------------------------|
|  Kilometers | 80791 |  Specs | Yes |
|  Engine | 1.2L |  Option Type | Fully Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | HATCHBACK |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Yellow |
|  Interior Trim | Partial Leather Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | VR3UPHNLXPT001131 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Comfort & Convenience | |
|--|---|
| Climate Control AC |  |
| Steering Mounted Audio Controls |  |
| Rear Defogger |  |
| Automatic Headlights |  |
|  Safety & Security | |

| | | | |
|----------------------|---|--------------------------|---|
| Navigation |  | Parking Sensors Front |  |
| Parking Sensors Rear |  | Reverse Camera |  |
| Blind Spot Monitor |  | Collision Warning System |  |
| Traction Control |  | Airbag Curtain Shield |  |
| Airbag Driver Front |  | ABS |  |
| Central Locking |  | Child Safety Locking |  |



Exteriors

| | | | |
|----------------|---|---------------------|---|
| Running Lights |  | Rear Bumper Spoiler |  |
| LED Headlights |  | | |



Entertainment

| | | | |
|---------------------|---|-------------------|---|
| Bluetooth Player |  | Apple Play |  |
| Android Auto Play |  | USB Charging Port |  |
| Infotainment System |  | USB player |  |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



| | | | |
|--------------------------------------|---|------------------------------|---|
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | | | |
| Condition: Passenger Side/Stone Chip | ! | Rear Windshield | ✓ |
| Mark>8mm | | | |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

Engine

| | | | |
|--------------------------------|--|--------------------|--|
| Engine Body | | Engine Performance | |
| Engine Oil (Condition & Level) | | Exhaust System | |
| Turbocharger/ Supercharger | | Radiator Condition | |
| Radiator Coolant | | | |
| Fuel System | | | |
| Fuel Tank | | | |
| Transmission Operation | | | |
| Gear Shifting | | Drive Axle | |
| Transmission Fluid | | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|--|-----------------------|--|
| Steering | | | |
| Steering wheel | | | |
| Brake System | | | |
| Parking Brake | | Brake Master Cylinder | |
| Brake Disc & Brake Pad | | Brake Fluid | |
| Suspension | | | |
| Shock Absorbers | | | |

Electricals, Controls & Lights

| | | | |
|----------------------|--|--------------|--|
| Keys | | | |
| Master Key | | Spare Key(s) | |
| Door Locks | | | |
| Child Safety Locking | | | |
| Dashboard | | | |
| Instrument Panel | | | |
| Airbags | | | |
| Airbags | | | |

| | | | |
|-----------------------|---|-------------------------|---|
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Radar (If Equipped) | ✓ | Navigation System | ✓ |
| Music System | ✓ | | |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Glove Box | ✓ | Steering Wheel | ✓ |
| Sunvisor | ✓ | Seat Upholstery | ✓ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Head Rest | ✓ | Door Controls And Trim | ✓ |

| | | | |
|-------------|--|------------------|--|
| Grab Handle | | Carpet | |
| Headliner | | Rear View Mirror | |
| Toolkit | | | |

Tyres

Tyres Condition

| | | | |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre | | Left Hand Side Rear Tyre | |
| Right Hand Side Front Tyre | | Right Hand Side Rear Tyre | |
| Spare Tyre | | | |
| Life remaining | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <85% | RHS Rear Tyre | <85% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE