



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 VOLKSWAGEN T ROC

R LINE | 30,170 KM

VIN: WVGC1A18PV725711

## Car highlights



### Panoramic Roof

This car has a panoramic roof



### Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

## Basic Details

|  |                             |   |                            |
|--|-----------------------------|---|----------------------------|
|  Kilometers       | <b>30170</b>                |  Specs             | <b>Yes</b>                 |
|  Engine           | <b>1.4L</b>                 |  Option Type       | <b>Fully Loaded</b>        |
|  Transmission     | <b>Automatic</b>            |  Drive             | <b>Front Wheel Drive</b>   |
|  Body Type        | <b>SUV</b>                  |  Fuel              | <b>Petrol</b>              |
|  Wheel Type       | <b>Alloy Wheels</b>         |  Exterior Color    | <b>Exterior Color Blue</b> |
|  Interior Trim    | <b>Partial Leather Trim</b> |  Number of Airbags | <b>6 Airbags</b>           |
|  Seating Capacity | <b>5 Seats</b>              |  Number of keys    | <b>2 Keys</b>              |
|  VIN number     | <b>WVGCD1A18PV725711</b>    |   |                            |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Safety & Security |   |                       |   |
|---|---|-----------------------|---|
| Adaptive cruise control   |  | Navigation            |  |
| Parking Sensors Front   |  | Parking Sensors Rear  |  |
| Auto Park Assist  |  | Reverse Camera        |  |
| Traction Control  |  | Airbag Curtain Shield |  |
| Airbag Driver Front   |  | ABS                   |  |

|                                  |   |                                 |   |
|----------------------------------|---|---------------------------------|---|
| Central Locking                  |     | Child Safety Locking            |     |
| <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Climate Control AC               |    | Cruise Control                  |    |
| Rear Armrest with cupholder      |    | Steering Mounted Audio Controls |    |
| Power Folding Mirrors            |    | Power Tailgate/ Power Trunk     |    |
| Rear Defogger                    |    | Central Armrest                 |    |
| Automatic Headlights             |    | Steering Column Adjuster        |    |
| <b>Performance</b>               |   |                                 |   |
| Paddle Shift                     |    |                                 |   |
| <b>Exteriors</b>                 |   |                                 |   |
| Roof Rails                       |  | Running Lights                  |  |
| Rear Bumper Spoiler              |  | LED Headlights                  |  |
| <b>Entertainment</b>             |   |                                 |   |
| Bluetooth Player                 |  | Apple Play                      |  |
| Android Auto Play                |  | USB Charging Port               |  |
| Infotainment System              |  | USB player                      |  |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Condition: Dent

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Trim: Light Scuffing<80mm

Condition: Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Scuffing > 80mm, Light

Scuffing < 80mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



|  |   |                              |   |
|--|---|------------------------------|---|
| Left A to B Pillar Beading                 | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar                        | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim                         | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim                        | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading                | ✓ | Left C Pillar                | ✓ |
| Running Board Condition                    |   |                              |   |
| Left Running Board                         | ✓ | Right Running Board          | ✓ |
| Sunroof Glass Condition (If Equipped)      |   |                              |   |
| Sun Roof Glass                             | ✓ |                              |   |
| Windshield Condition                       |   |                              |   |
| Front Windshield                           |   | Rear Windshield              | ✓ |
| Condition: Driver Side/Stone Chip Mark<5mm | ! |                              |   |
| Structural Assessment                      |   |                              |   |
| Chassis Condition                          | ✓ | Apron                        | ✓ |
| Boot Floor                                 | ✓ | Firewall Condition           | ✓ |
| Cowl Top                                   | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                                   |   |                              |   |
| Cowl Top                                   | ✓ |                              |   |
| Rear View Mirror Condition                 |   |                              |   |
| Left Hand Side Mirror                      | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                          | ✓ |                              |   |
| Alloy Wheel/ Rim                           |   |                              |   |
| Left Front Alloy/ Rim                      | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim                     | ✓ | Right Rear Alloy/ Rim        | ! |
|  |   | Rim: Alloy Face/Scuffing     |   |
| Spare Alloy/ Rim Condition                 | ✓ |                              |   |
| Antenna                                    | ✓ | Grill Condition              | ✓ |
| Monogram                                   | ✓ | Window Glass                 | ✓ |

Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Colour Faded

Front Right AC Vent



Heater



Rear Blower Switch



Knob Restricted Movement

Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



|                              |  |                      |  |
|------------------------------|--|----------------------|--|
| Cup Holder                   |  | Glove Box            |  |
| Steering Wheel               |  | Sunvisor             |  |
| Steering Wheel Fair Use Wear |  |                      |  |
| Seat Upholstery              |  | Manual Seat Movement |  |
| Seat Belts                   |  | Head Rest            |  |
| Door Controls And Trim       |  | Grab Handle          |  |
| Carpet                       |  | Headliner            |  |
| Rear View Mirror             |  | Toolkit              |  |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  |      | Left Hand Side Rear Tyre  |      |
| Right Hand Side Front Tyre |      | Right Hand Side Rear Tyre |      |
| Spare Tyre                 |      |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <75% | RHS Rear Tyre             | <75% |
| Spare Tyre                 | <55% |                           |      |



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE