



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2017 FORD EXPLORER

XLT | 113,974 KM

VIN: 1FM5K8D89HGA51977

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	113974	 Specs	Yes
 Engine	3.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel Efficiency	9.8 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	1FM5K8D89HGA51977		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Steering Mounted Audio Controls	
Rear Defogger	
Remote Engine Start	
Steering Column Adjuster	
Cruise Control	
Power Tailgate/ Power Trunk	
Central Armrest	
Automatic Headlights	



Exteriors

Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
LED Headlights	✓	Halogen Headlights	✓



Performance

Paddle Shift	✓	Hill Descent Control	✓
--------------	---	----------------------	---



Safety & Security

Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Traction Control	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		



Entertainment

Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing, Low Visual Dent

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Scuffing > 50mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip			
Mark<5mm, Passenger Side/Stone Chip	!	Rear Windshield	✓
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror			
Body: Light Scuffing	!		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	!

Light Scuffing < 50mm

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking	✓	
Dashboard	✓	
Instrument Panel	✓	
Airbags	✓	
Airbags	✓	
Controls	✓	Cruise Control
Infotainment Display	✓	OBD Connector
Music System	✓	
Sunroof Operation		
Sunroof	✓	
Camera	✓	
Lights		
Headlight	✓	Interior Lights
Tail Light Cluster	✓	Daylight Running Lights
License Plate Light	✓	
Air Conditioning		
AC Cooling	✓	AC Switch
AC System Leaks	✓	Center AC Vent
Front Right AC Vent	✓	Heater
Rear Blower Switch	✓	Rear Left AC Vent
Rear Defogger	✓	USB Charging Port
Power/ Manual Windows	✓	

Interiors & Luggage

Dashboard And Instrument Panel		
Dashboard Upholstery: Minor Color Dullness	!	Central Console
Glove Box	✓	Steering Wheel

Sunvisor		Seat Upholstery	
Manual Seat Movement		Seat Belts	
Head Rest		Door Controls And Trim	
Grab Handle		Carpet	
Headliner		Rear View Mirror	
Toolkit			

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE