



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 TOYOTA FJ CRUISER**

**GXR | 102,988 KM**

VIN: JTEBU11F3NK266951

## Car highlights



### **Power packed**

Engine size of 4.0 Litres & 6.0 cylinders



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>102988</b>	 Specs	<b>Yes</b>
 Engine	<b>4.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	Fuel Efficiency	<b>8.0 km/L mileage</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Blue</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>JTEBU11F3NK266951</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side			
 <b>Safety &amp; Security</b>			
Navigation		Parking Sensors Rear	
Reverse Camera		Airbag Driver Front	

Airbag Passenger Front



ABS



**Performance**

Differential Locks



**Entertainment**

Bluetooth Player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front right door

Panel: Light Scuffing < 50mm



Rear left door



Rear right door



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood



### Running Board Condition

Left Running Board



Right Running Board



### Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip

Mark<5mm, Passenger Side/Stone Chip

Mark<8mm



Rear Windshield



### Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Grill Condition

Light Scuffing < 50mm



Panel Condition

Rear Trunk Panel



---

## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



---

## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



---

## Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel



Controls		Infotainment Display	
Music System		Camera	
Condition: Missing Control Knob			
Lights			
Headlight		Tail Light Cluster	
Air Conditioning			
AC Cooling		AC System Leaks	
Power/ Manual Windows			

### Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear			
Steering Wheel		Headliner	
Toolkit			

### Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<73%	LHS Rear Tyre	<73%
RHS Front Tyre	<73%	RHS Rear Tyre	<73%
Spare Tyre	<15%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE