



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 MITSUBISHI ATTRAGE

GLX HIGHLINE | 22,756 KM

VIN: MMADAFT6J1SH002091

## Car highlights

### Fuel Efficient

Fuel efficient with 20.2 km/L



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

|  |                          |   |                            |
|--|--------------------------|---|----------------------------|
|  Kilometers       | <b>22756</b>             |  Specs             | <b>Yes</b>                 |
|  Engine           | <b>1.2L</b>              |  Option Type       | <b>Fully Loaded</b>        |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>Front Wheel Drive</b>   |
|  Body Type        | <b>SEDAN</b>             | Fuel Efficiency   | <b>20.2 km/L mileage</b>   |
|  Wheel Type       | <b>Alloy Wheels</b>      |  Exterior Color    | <b>Exterior Color Grey</b> |
|  Interior Trim    | <b>Fabric Trim</b>       |  Number of Airbags | <b>2 Airbags</b>           |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>2 Keys</b>              |
|  VIN number      | <b>MMDAFT6J1SH002091</b> |   |                            |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |
|--|---|
|  <b>Exteriors</b>                 |   |
| Fog Light Front  |  |
|  <b>Comfort &amp; Convenience</b> |   |
| Cruise Control   |  |
| Rear Defogger  |  |
|  <b>Entertainment</b>             |   |

|  |   |                     |   |
|--|---|---------------------|---|
| Bluetooth Player   |   | USB player          |   |
|  <b>Safety &amp; Security</b> |   |                     |   |
| Airbag Curtain Shield  |  | Airbag Driver Front |  |
| ABS  |  |                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Condition: Scuffing

Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Light Scuffing < 50mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   |                              |   |
| Light Scuffing < 50mm       | ! | Monogram                     | ✓ |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |

## Engine & Transmission

### Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

### Fuel System

Fuel Tank 

### Transmission Operation

Gear Shifting  Gear shift 

Drive Axle  Transmission Fluid 

## Steering, Suspension & Brakes

### Steering

Steering wheel 

### Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

### Suspension

Shock Absorbers 

## Electricals, Controls & Lights

### Keys

Master Key  Spare Key(s) 

### Door Locks

Child Safety Locking 

### Dashboard

Instrument Panel 

### Airbags

Airbags 

|                     |   |                         |   |
|---------------------|---|-------------------------|---|
| Controls            | ✓ | Cruise Control          | ✓ |
| Heads Up Display    | ✓ | Infotainment Display    | ✓ |
| OBD Connector       | ✓ | Navigation System       | ✓ |
| Music System        | ✓ |                         |   |
| Sunroof Operation   |   |                         |   |
| Sunroof             | ✓ |                         |   |
| Camera              | ✓ |                         |   |
| Lights              |   |                         |   |
| Headlight           | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster  | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ |                         |   |
| Air Conditioning    |   |                         |   |
| AC Cooling          | ✓ | AC Switch               | ✓ |
| AC System Leaks     | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent | ✓ | Heater                  | ✓ |
| Rear Blower Switch  | ✓ |                         |   |
| USB Charging Port   | ✓ | Power/ Manual Windows   | ✓ |
| Memory Seats        | ✓ |                         |   |

## **Interiors & Luggage**

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |

Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<73%

LHS Rear Tyre

<90%

RHS Front Tyre

<90%

RHS Rear Tyre

<73%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE