



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 SUZUKI JIMNY

GLX | 98,670 KM

VIN: MA3JB7D27P0122946

## Car highlights



### Great condition

Car has low imperfections



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Music System

Enjoy your drive with music system



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>98670</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel Efficiency	<b>13.3 km/L mileage</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Green</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>4 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>MA3JB7D27P0122946</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Power Window front - Drivers Side	
Power Window front - Passenger Side	
 <b>Exteriors</b>	
Fog Light Front	
Running Lights	
 <b>Safety &amp; Security</b>	

Navigation	✓	Reverse Camera	✓
Airbag Sides	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		

 **Performance**

Hill Descent Control	✓	Differential Locks	✓
----------------------	---	--------------------	---

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition



Front right door

Fenders Condition



Left Fender



Right Fender

Quarter Panels Condition



Left Quarter Panel



Right Quarter Panel

Rear Bumper Condition



Rear Bumper

Hood Condition



Hood

Running Board Condition



Left Running Board



Right Running Board

Windshield Condition



Front Windshield



Rear Windshield

Structural Assessment



Chassis Condition

Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top



Alloy Wheel/ Rim



Left Front Alloy/ Rim



Left Rear Alloy/ Rim

Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Grill Condition



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel



Controls



Infotainment Display



Music System



Camera



## Lights

Headlight  Tail Light Cluster 

Daylight Running Lights 

Air Conditioning

AC Cooling 

Power/ Manual Windows 

## Interiors & Luggage

Dashboard And Instrument Panel  Central Console 

Steering Wheel  Headliner 

## Tyres

Tyres Condition

Left Hand Side Front Tyre  Left Hand Side Rear Tyre 

Right Hand Side Front Tyre  Right Hand Side Rear Tyre 

Spare Tyre 

Life remaining

LHS Front Tyre	<35%	LHS Rear Tyre	<35%
----------------	------	---------------	------

RHS Front Tyre	<35%	RHS Rear Tyre	<35%
----------------	------	---------------	------

Spare Tyre	<55%
------------	------



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE