



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 GEELY COOLRAY**

**GF | 23,161 KM**

VIN: LB3762KZ1RX516348

## **Car highlights**



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort



### **Apple play**

Enjoy your drive with apple play

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Amazing Comfort**

Power driver seat, Ventilated Seats

## Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 23161             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number       | LB3762KZ1RX516348 |                                                                                                     |                      |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                       |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------|
| <div> Safety &amp; Security</div> |                                                                                     |                       |                                                                                       |
| Adaptive cruise control                                                                                              |  | 360 degree Camera     |  |
| Lane Departure Warning System                                                                                        |  | Parking Sensors Front |  |
| Parking Sensors Rear                                                                                                 |  | Auto Park Assist      |  |
| Reverse Camera                                                                                                       |  | Blind Spot Monitor    |  |
| Collision Warning System                                                                                             |  | Front Camera          |  |

|                                                                                                                    |   |                                     |   |
|--------------------------------------------------------------------------------------------------------------------|---|-------------------------------------|---|
| Side Camera                                                                                                        | ✓ | Airbag Curtain Shield               | ✓ |
| Airbag Driver Front                                                                                                | ✓ | Airbag Passenger Front              | ✓ |
| ABS                                                                                                                | ✓ |                                     |   |
|  <b>Comfort &amp; Convenience</b> |   |                                     |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control                      | ✓ |
| Power Window front - Drivers Side                                                                                  | ✓ | Power Window front - Passenger Side | ✓ |
| Ventilated Seat                                                                                                    | ✓ | Power Tailgate/ Power Trunk         | ✓ |
| Power Windows Rear                                                                                                 | ✓ |                                     |   |
|  <b>Exteriors</b>                 |   |                                     |   |
| Roof Rails                                                                                                         | ✓ | Running Lights                      | ✓ |
| Rear Bumper Spoiler                                                                                                | ✓ |                                     |   |
|  <b>Performance</b>             |   |                                     |   |
| Hill Descent Control                                                                                               | ✓ |                                     |   |
|  <b>Entertainment</b>           |   |                                     |   |
| Bluetooth Player                                                                                                   | ✓ | Apple Play                          | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                  |                                                                                   |                |                                                                                     |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door |  | Rear left door |  |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|

|                 |                                                                                   |
|-----------------|-----------------------------------------------------------------------------------|
| Rear right door |  |
|-----------------|-----------------------------------------------------------------------------------|

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                    |                                                                                     |
|------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper                        |  |
| Rear Bumper: Light Scuffing < 80mm |                                                                                     |

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Sunroof Glass Condition (If Equipped)

|                |                                                                                     |
|----------------|-------------------------------------------------------------------------------------|
| Sun Roof Glass |  |
|----------------|-------------------------------------------------------------------------------------|

### Windshield Condition

|                  |                                                                                     |                 |                                                                                       |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield |  | Rear Windshield |  |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                   |                                                                                     |       |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Apron |  |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|

|            |                                                                                     |                    |                                                                                       |
|------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|
| Boot Floor |  | Firewall Condition |  |
|------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|

|                              |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|
| Head Light Support Condition |  |
|------------------------------|-------------------------------------------------------------------------------------|

### Cowl Top

|          |                                                                                     |
|----------|-------------------------------------------------------------------------------------|
| Cowl Top |  |
|----------|-------------------------------------------------------------------------------------|

|                        |   |                         |
|------------------------|---|-------------------------|
| Alloy Wheel/ Rim       |   |                         |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim ✓  |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim ✓ |
| Panel Condition        |   |                         |
| Rear Trunk Panel       | ✓ |                         |


**Engine & Transmission**

|                                |   |                      |
|--------------------------------|---|----------------------|
| Engine                         |   |                      |
| Engine Body                    | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓     |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition ✓ |
| Radiator Coolant               | ✓ |                      |
| Transmission Operation         |   |                      |
| Gear Shifting                  | ✓ | Drive Axle ✓         |


**Steering, Suspension & Brakes**

|                 |   |                         |
|-----------------|---|-------------------------|
| Brake System    |   |                         |
| Parking Brake   | ✓ | Brake Master Cylinder ✓ |
| Brake Fluid     | ✓ |                         |
| Suspension      |   |                         |
| Shock Absorbers | ✓ |                         |


**Electricals, Controls & Lights**

|                  |   |                        |
|------------------|---|------------------------|
| Keys             |   |                        |
| Master Key       | ✓ |                        |
| Dashboard        |   |                        |
| Instrument Panel | ✓ |                        |
| Controls         | ✓ | Infotainment Display ✓ |
| Music System     | ✓ | Camera ✓               |
| Lights           |   |                        |

|                         |   |                    |   |
|-------------------------|---|--------------------|---|
| Headlight               | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ |                    |   |
| Air Conditioning        |   |                    |   |
| AC Cooling              | ✓ | AC System Leaks    | ✓ |
| Power/ Manual Windows   | ✓ |                    |   |

### Interiors & Luggage

|                                |   |                |   |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner                      | ✓ | Toolkit        | ✓ |

### Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <55% | LHS Rear Tyre             | <55% |
| RHS Front Tyre             | <55% | RHS Rear Tyre             | <55% |
| Spare Tyre                 | <55% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE