



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 TOYOTA RAIZE

G | 83,349 KM

VIN: MHKAA1BA2PJ091019

## Car highlights

### Service History

Service history available



### Great Parking Assistance

Reverse Camera, Parking Sensors Rear

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>83349</b>	 Specs	<b>Yes</b>
 Engine	<b>1.0L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Blue</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>MHKAA1BA2PJ091019</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Exteriors			

Running Lights



LED Headlights



### Comfort & Convenience

Steering Mounted Audio  
Controls



Rear Defogger



Central Armrest



Automatic Headlights



Steering Column Adjuster



### Entertainment

Bluetooth Player



Apple Play



USB Charging Port



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Low Visibility Dent < 30mm, Light

Scuffing < 50mm

Rear left door



Rear right door



Fenders Condition

Left Fender



Condition: Dent, Scuffing

Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Chip < 8mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	!		
Body: Light Scuffing			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	!		
Scuffing > 50mm		Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags		
Airbags	✓	
Controls	✓	Cruise Control
Infotainment Display	✓	OBD Connector
Music System	✓	Camera
Lights		
Headlight	✓	Interior Lights
Tail Light Cluster	✓	Daylight Running Lights
		Fog Lights
License Plate Light	✓	Right Fog Light: Cracks/ Holes/ Fair Use Wear
Air Conditioning		
AC Cooling	✓	AC Switch
AC System Leaks	✓	Center AC Vent Scuffing
Front Right AC Vent	✓	Heater
Rear Blower Switch	✓	
Parking Sensors	✓	USB Charging Port
Power/ Manual Windows	✓	Memory Seats

## **Interiors & Luggage**

Dashboard And Instrument Panel		
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Central Console
Cup Holder	✓	Glove Box
		Sunvisor
Steering Wheel	✓	Left: Sunvisor LHS Minor Disfiguration, Sunvisor RHS Minor Disfiguration
Seat Upholstery	✓	Manual Seat Movement

Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet Front Left Floor Mat: Smudge/Burn/Crack		Headliner	
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

### Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE