



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 NISSAN SENTRA

SV | 39,203 KM

VIN: MNTBB7A91K6065280

Car highlights



Low Mileage

This car has been driven less than 15,000 km
a year



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	39203	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel Efficiency	15.2 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MNTBB7A91K6065280		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Exteriors			

Rear Bumper Spoiler



Halogen Headlights



Comfort & Convenience

Steering Mounted Audio
Controls



Rear Defogger



Central Armrest



Steering Column Adjuster



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender

Condition: Dent



Right Fender: Light Scuffing

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent, Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Bonnet: Light Scuffing < 50mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Condition: Driver Side/Scuffing		Front Right Sill Trim: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield		Rear Windshield	
Condition: Driver Side/Scuffing			
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Body: Light Scuffing			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Wheel cover		Grill Condition	
Monogram		Window Glass	
Wiper			
Panel Condition			
Rear Trunk Panel			

Engine & Transmission

Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

Fuel System

Fuel Tank 

Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

Suspension

Shock Absorbers 

Electricals, Controls & Lights

Keys

Master Key  Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls	✓	Infotainment Display	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	!	Interior Lights	✓
Left: Light Scuff Marks < 50mm			
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	!
		Gear Shift Knob: Buttons Faded	
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

 **Tyres**

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE