



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 TOYOTA YARIS**

**SE | 65,451 KM**

**VIN: MHFB29F39N2177574**

## **Car highlights**

### **Fuel Efficient**

Fuel efficient with 18.8 km/L



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>65451</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel Efficiency	<b>18.8 km/L mileage</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>MHFB29F39N2177574</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Defogger	
Central Armrest		Steering Column Adjuster	
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	

Central Locking



Child Safety Locking



**Entertainment**

Bluetooth Player



USB player



**Exteriors**

Halogen Headlights



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Handle: Scuffing > 50mm

Rear left door



Rear right door



Panel: Scuffing

Handle: Scratch > 50mm

Fenders Condition

Left Fender

Condition: Fender liner missing/ damaged/  
misaligned



Right Fender



Right Fender: Light Scuffing

Quarter Panels Condition

Left Quarter Panel

Condition: Scuffing



Right Quarter Panel



Condition: Light Scuffing, Chip, Low Visual  
Dent

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar Condition: Scuffing	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Front Left Sill Trim: Scuffing > 100mm			
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip		Rear Windshield	
Mark<5mm, Passenger Side/Stone Chip			
Mark<8mm			
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition			
Wheel cover		Antenna	
Grill Condition		Monogram	
Scuffing > 50mm			
Window Glass		Wiper Front Left: Crack/ Fair Use Wear	

Panel Condition

Rear Trunk Panel

Dent



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Cable Major Loose

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags		
Airbags	✓	
Controls	✓	Cruise Control
Infotainment Display	✓	OBD Connector
Music System	✓	
Lights		
Headlight	✓	Interior Lights
Tail Light Cluster	✓	License Plate Light
Air Conditioning		
AC Cooling	✓	AC Switch Missing Control Knob
AC System Leaks	✓	Center AC Vent
Front Right AC Vent	!	Heater
Adjuster Clip Crack/Fair Use Wear		
Rear Defogger	✓	USB Charging Port
Power/ Manual Windows	✓	

## Interiors & Luggage

Dashboard And Instrument Panel		
Dashboard Upholstery: Scuffing/ Disfiguration/ Melted	!	Central Console Box: Crack/Fair Use Wear/ Scuffing
Glove Box	✓	Steering Wheel
Sunvisor	✓	Seat Upholstery
Manual Seat Movement	✓	Seat Belts
Head Rest	✓	Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration
Grab Handle	✓	Carpet
Headliner	✓	Rear View Mirror



## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

### Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE