



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 RENAULT DUSTER

LE | 84,177 KM

VIN: VF1HSRMX8PA048938

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

360° camera, Reverse Camera & more

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	84177	 Specs	Yes
 Engine	1.6L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel Efficiency	15.3 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	VF1HSRMX8PA048938		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Navigation	
Parking Sensors Rear		Reverse Camera	
Airbag Sides		Airbag Driver Front	
Airbag Passenger Front			
 Comfort & Convenience			

Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		



Exteriors

Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Scuffing >



50mm

Fenders Condition

Left Fender



Right Fender



Right Fender: Scuffing

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Dent, Scuffing/ Scratch

Rear Bumper Condition

Rear Bumper



Rear Bumper: Fully Repainted

Hood Condition

Hood



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
Cowl Top	✓		
Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	!		
Scuffing > 50mm			
Panel Condition			
Rear Trunk Panel	✓		

⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

🌐 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key 

Dashboard

Instrument Panel 

Controls 

Infotainment Display 

Music System 

Camera 

Lights

Headlight 

Tail Light Cluster 

Daylight Running Lights 

Air Conditioning

AC Cooling 

Rear Left AC Vent 

Rear Entertainment 

Power/ Manual Windows 

Memory Seats 

Interiors & Luggage

Central Console 

Steering Wheel 

Headliner 

Tyres

Tyres Condition

Left Hand Side Front Tyre 

Left Hand Side Rear Tyre 

Right Hand Side Front Tyre 

Right Hand Side Rear Tyre 

Spare Tyre 

Life remaining

LHS Front Tyre 

<35%

LHS Rear Tyre 

<35%

RHS Front Tyre 

<35%

RHS Rear Tyre 

<35%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE