



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 HYUNDAI KONA

SMART | 112,408 KM

VIN: KMHK281A1KU242120

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	112408	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Green
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	KMHK281A1KU242120		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Running Lights			
 Comfort & Convenience			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side		Power Windows Rear	



Safety & Security

Parking Sensors Rear		Reverse Camera	
Airbag Sides		Airbag Curtain Shield	
Airbag Driver Front		Airbag Passenger Front	
ABS			



Performance

Hydraulic Suspensions		Hill Descent Control	
-----------------------	--	----------------------	--

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Rear Bumper: Scuffing > 80mm, Crack/

Misaligned, Replaced, Fully Repainted

Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor

Condition: Rear Reinforcement bar dent



Firewall Condition



Head Light Support Condition



Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Grill Condition			
Light Scuffing < 50mm			
Panel Condition			
Rear Trunk Panel			

Engine & Transmission

Engine			
Engine Body			
Damage & Leaks: Mountings weak		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Transmission Operation			
Gear Shifting			
Mountings weak		Drive Axle	

Steering, Suspension & Brakes

Brake System			
Parking Brake		Brake Master Cylinder	
Brake Fluid			
Suspension			
Shock Absorbers			

Electricals, Controls & Lights

Keys			
Master Key			
Dashboard			
Instrument Panel			
Controls		Music System	
Camera			

Lights

Headlight  Tail Light Cluster 

Daylight Running Lights 

Air Conditioning

AC Cooling 

Interiors & Luggage

Dashboard And Instrument Panel  Steering Wheel 
Color Faded

Headliner 

Tyres

Tyres Condition

Left Hand Side Front Tyre  Left Hand Side Rear Tyre 

Right Hand Side Front Tyre  Right Hand Side Rear Tyre 

Spare Tyre 

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<55%
----------------	------	---------------	------

RHS Front Tyre	<55%	RHS Rear Tyre	<55%
----------------	------	---------------	------

Spare Tyre	<65%
------------	------



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE