

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 SUZUKI SWIFT

GLX | 119,041 KM

Car highlights

Fuel Efficient

Fuel efficient with 17.9 km/L

Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	119041	Specs	Yes
Engine	1.2L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	HATCHBACK	Fuel Efficiency	17.9 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Black
Interior Trim	Fabric Trim	Number of Airbags	6 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	JS2ZC6C26N6400508		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
Exteriors			
Fog Light Front	✓	Running Lights	✓

Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Airbag Sides	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		

Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm	Rear left door Panel: Scuffing
Rear right door	

Fenders Condition

Left Fender Condition: Light Scuffing	Right Fender

Quarter Panels Condition

Left Quarter Panel Condition: Dent	Right Quarter Panel Condition: Light Scuffing, Low Visual Dent

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood
Bonnet: Paint Chip-off < 5mm

Running Board Condition

Left Running Board	Right Running Board

Windshield Condition

Front Windshield Condition: Driver Side/Stone Chip Mark<5mm	Rear Windshield

Structural Assessment

Chassis Condition	Apron
Boot Floor	Firewall Condition
Head Light Support Condition	

Cowl Top

Cowl Top

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Grill Condition

Fully Repainted

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Turbocharger/ Supercharger

Radiator Condition

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake

Brake Master Cylinder

Brake Fluid

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Controls	✓	Infotainment Display	✓
Music System	✓	Camera	✓

Lights

Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		

Air Conditioning

AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Steering Wheel	✓
Headliner Front Left: Light Smudge/Disfiguration	!	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%
Spare Tyre	<35%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE