



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 NISSAN PATROL**

**SE TITANIUM | 30,337 KM**

VIN: JN8BY2NY8R9446177

## Car highlights



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort



### **Apple play**

Enjoy your drive with apple play

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Amazing Comfort**

Power driver seat

## Basic Details

|  |                          |   |                            |
|--|--------------------------|---|----------------------------|
|  Kilometers       | <b>30337</b>             |  Specs             | <b>Yes</b>                 |
|  Engine           | <b>4.0L</b>              |  Option Type       | <b>Semi Loaded</b>         |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>Four Wheel Drive</b>    |
|  Body Type        | <b>SUV</b>               | Fuel Efficiency   | <b>6.5 km/L mileage</b>    |
|  Wheel Type       | <b>Alloy Wheels</b>      |  Exterior Color    | <b>Exterior Color Grey</b> |
|  Interior Trim    | <b>Leather Trim</b>      |  Number of Airbags | <b>8 Airbags</b>           |
|  Seating Capacity | <b>8 Seats</b>           |  Number of keys    | <b>2 Keys</b>              |
|  VIN number      | <b>JN8BY2NY8R9446177</b> |   |                            |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  <b>Safety &amp; Security</b> |   |                               |   |
|--|---|-------------------------------|---|
| Adaptive cruise control  |  | Lane Departure Warning System |  |
| Navigation   |  | Parking Sensors Front         |  |
| Parking Sensors Rear   |  | Reverse Camera                |  |
| Blind Spot Monitor   |  | Collision Warning System      |  |
| Airbag Curtain Shield  |  | Airbag Driver Front           |  |

|  |   |                                     |   |
|--|---|-------------------------------------|---|
| Airbag Passenger Front   |     | ABS                                 |     |
|  <b>Comfort &amp; Convenience</b> |   |                                     |   |
| Climate Control AC   |    | Cruise Control                      |    |
| Power Window front - Drivers Side  |    | Power Window front - Passenger Side |    |
| Power Tailgate/ Power Trunk  |    | Cool Box                            |    |
| Power Windows Rear   |    |                                     |   |
|  <b>Exteriors</b>                 |   |                                     |   |
| Fog Light Front  |    | Roof Rails                          |    |
| Running Lights   |    | Rear Bumper Spoiler                 |    |
| Trailer Hook / Coupling  |    |                                     |   |
|  <b>Entertainment</b>           |   |                                     |   |
| Rear Seat Entertainment  |  | Bluetooth Player                    |  |
| Apple Play   |  | Android Auto Play                   |  |
|  <b>Performance</b>             |   |                                     |   |
| Hill Descent Control   |  | Differential Locks                  |  |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front right door



Rear left door

Panel: Colour faded



Rear right door



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel

Condition: Colour faded



Right Quarter Panel



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Dent < 50mm, Scuffing > 80mm



### Hood Condition

Hood



### Running Board Condition

Left Running Board



Right Running Board



### Sunroof Glass Condition (If Equipped)

Sun Roof Glass



### Windshield Condition

Front Windshield



Rear Windshield



### Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Panel Condition

Rear Trunk Panel



---

## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



---

## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



---

## Electricals, Controls & Lights

Keys

Master Key



Dashboard

|                         |   |                       |   |
|-------------------------|---|-----------------------|---|
| Instrument Panel        | ✓ |                       |   |
| Controls                | ✓ | Infotainment Display  | ✓ |
| Music System            | ✓ | Camera                | ✓ |
| Lights                  |   |                       |   |
| Headlight               | ✓ | Tail Light Cluster    | ✓ |
| Daylight Running Lights | ✓ |                       |   |
| Air Conditioning        |   |                       |   |
| AC Cooling              | ✓ | AC System Leaks       | ✓ |
| Rear Left AC Vent       | ✓ |                       |   |
| Rear Entertainment      | ✓ | Power/ Manual Windows | ✓ |

### Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel                 | ✓ | Headliner       | ✓ |
| Toolkit                        | ✓ |                 |   |

### Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <55% | LHS Rear Tyre             | <55% |
| RHS Front Tyre             | <55% | RHS Rear Tyre             | <55% |
| Spare Tyre                 | <55% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE