


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2022 MITSUBISHI ASX**

**GLX M/L SIGNATURE EDITION | 56,791 KM**

VIN: JE4LPT1U9NU704117

## Car highlights

### Cruise control

Cruise control to drive with ease & comfort

### Bluetooth

Enjoy your drive with bluetooth

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 56791 | Specs | Yes |
| Engine | 2.0L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | SUV | Fuel | Petrol |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color White |
| Interior Trim | Leather Trim | Number of Airbags | 2 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 2 Keys |
| VIN number | JE4LPT1U9NU704117 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|---|---|
| **Comfort & Convenience** | | | |
| Cruise Control | ✓ | Power Window front - Drivers Side | ✓ |
| Power Window front - Passenger Side | ✓ | Power Windows Rear | ✓ |
| **Safety & Security** | | | |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Blind Spot Monitor | ✓ | Airbag Driver Front | ✓ |

| | | | |
|---|---|---|---|
| Airbag Passenger Front | ✓ | ABS | ✓ |
| **Entertainment** | | | |
| Rear Seat Entertainment | ✓ | Bluetooth Player | ✓ |
| **Exteriors** | | | |
| Running Lights | ✓ | Rear Bumper Spoiler | ✓ |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

### Doors condition

| | | | |
|---|---|---|---|
| Front right door<br>Panel: Light Scuffing < 50mm, Door inner sealant repaired / corroded / damaged | ! | Rear left door | ✓ |
| Rear right door<br>Panel: Light Scuffing < 50mm, Paint Defect, Door inner sealant repaired / corroded / damaged | ! | | |

### Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender | ✓ | Right Fender<br>Right Fender: Scuffing | ! |

### Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |

### Rear Bumper Condition

| | | | |
|---|---|---|---|
| Rear Bumper<br>Rear Bumper: Fully Repainted, Crack/ Misaligned, Scuffing > 80mm, Dent > 50mm | ! | | |

### Hood Condition

| | | | |
|---|---|---|---|
| Hood | ✓ | | |

### Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

### Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield<br>Condition: Front Wiper blades need replacement, Rear wiper blades need replacement, Driver Side/Stone Chip Mark<5mm | ! | Rear Windshield | ✓ |

### Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |

| | | | |
|---|---|---|---|
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Head Light Support Condition | ✓ | | |

Cowl Top

| | |
|---|---|
| Cowl Top | ✓ |

Alloy Wheel/ Rim

| | | | |
|---|---|---|---|
| Left Front Alloy/ Rim | ✓ | Right Front Alloy/ Rim<br>Rim: Alloy Face Scuffing | ! |

| | |
|---|---|
| Grill Condition<br>Fully Repainted | ! |

Panel Condition

| | |
|---|---|
| Rear Trunk Panel | ✓ |

## Engine & Transmission

Engine

| | | | |
|---|---|---|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |

Transmission Operation

| | | | |
|---|---|---|---|
| Gear Shifting | ✓ | Drive Axle | ✓ |

## Steering, Suspension & Brakes

Brake System

| | | | |
|---|---|---|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid | ✓ | | |

## Electricals, Controls & Lights

Keys

| | |
|---|---|
| Master Key | ✓ |

Dashboard

| | |
|---|---|
| Instrument Panel | ✓ |

| | | | |
|---|---|---|---|
| Controls | ✓ | Infotainment Display | ✓ |

| | | | |
|---|---|---|---|
| Music System | ✓ | Camera | ✓ |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ | | |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | AC System Leaks | ✓ |

Rear Entertainment

| | | | |
|---|---|---|---|
| Left Seat LCD: Remote Functions not Responding | ! | Power/ Manual Windows | ✓ |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner | ✓ | Toolkit | ✓ |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <35% | LHS Rear Tyre | <35% |
| RHS Front Tyre | <73% | RHS Rear Tyre | <35% |
| Spare Tyre | <35% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE