



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 KIA PEGAS

LX | 115,657 KM

VIN: LJD0AA29XN0179104

Car highlights

Fuel Efficient

Fuel efficient with 18.2 km/L



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	115657	 Specs	Yes
 Engine	1.4L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	18.2 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LJD0AA29XN0179104		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors		
Fog Light Front		
 Comfort & Convenience		
Cruise Control		Power Window front - Drivers Side 
Power Window front - Passenger Side		Power Windows Rear 
 Safety & Security		

Parking Sensors Rear 	Airbag Driver Front 
Airbag Passenger Front 	ABS 
 Entertainment	
Bluetooth Player 	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door
Panel: Paint Defect



Rear left door
Panel: Colour faded



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel
Condition: Colour faded



Right Quarter Panel
Condition: Light Scuffing



Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood
Bonnet: Acid Marks/ Bird Dropping < 5mm



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	!		
Light Scuffing < 50mm			
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓
Music System	✓		
Lights			

Headlight	✓	Tail Light Cluster	✓
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Left AC Vent	✓		

Interiors & Luggage

Dashboard And Instrument Panel		Steering Wheel	
Dashboard Upholstery: Scuffing/Crack/ Fair Use Wear	!	Color Faded	!
Headliner	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<90%	LHS Rear Tyre	<73%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%
Spare Tyre	<15%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE