



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 MG ONE**

**LUXURY | 49,500 KM**

VIN: LSJW94U98PN073922

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 49500             |  Specs             | Yes                 |
|  Engine           | 1.5L              |  Option Type       | Fully Loaded        |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 14.7 km/L mileage   |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | LSJW94U98PN073922 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                   |  |                                                                                                             |  |
|-------------------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------------------------------|--|
|  <b>Safety &amp; Security</b>  |  |                                                                                                             |  |
| Adaptive cruise control        |  | 360 degree Camera      |  |
| Lane Departure Warning System  |  | Parking Sensors Rear   |  |
| Reverse Camera                 |  | Blind Spot Monitor     |  |
| Front Camera                   |  | Side Camera            |  |
| Airbag Sides                   |  | Airbag Curtain Shield  |  |

|                                                                                                                    |   |                                     |   |
|--------------------------------------------------------------------------------------------------------------------|---|-------------------------------------|---|
| Airbag Driver Front                                                                                                | ✓ | Airbag Passenger Front              | ✓ |
| ABS                                                                                                                | ✓ |                                     |   |
|  <b>Comfort &amp; Convenience</b> |   |                                     |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control                      | ✓ |
| Power Window front - Drivers Side                                                                                  | ✓ | Power Window front - Passenger Side | ✓ |
| Power Windows Rear                                                                                                 | ✓ |                                     |   |
|  <b>Exteriors</b>                 |   |                                     |   |
| Roof Rails                                                                                                         | ✓ | Running Lights                      | ✓ |
| Rear Bumper Spoiler                                                                                                | ✓ |                                     |   |
|  <b>Performance</b>               |   |                                     |   |
| Hill Descent Control                                                                                               | ✓ |                                     |   |
|  <b>Entertainment</b>           |   |                                     |   |
| Bluetooth Player                                                                                                   | ✓ | Apple Play                          | ✓ |
| Android Auto Play                                                                                                  | ✓ |                                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door

Panel: Low Visibility Dent < 30mm



Rear left door



Rear right door

Panel: Light Scuffing < 50mm



### Fenders Condition

Left Fender

Condition: Light Scuffing



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm,  
Bumper Reflector Fair Use Wear/ Colour  
Faded



### Hood Condition

Hood



### Running Board Condition

Left Running Board



Right Running Board



### Sunroof Glass Condition (If Equipped)

Sun Roof Glass



### Windshield Condition

Front Windshield



Rear Windshield



### Structural Assessment

Chassis Condition



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Cowl Top               | ✓ |                       |   |
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## **Engine & Transmission**

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## **Steering, Suspension & Brakes**

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## **Electricals, Controls & Lights**

|                          |   |                      |   |
|--------------------------|---|----------------------|---|
| Keys                     |   |                      |   |
| Master Key               |   |                      |   |
| Manual Key Not Available | ! |                      |   |
| Dashboard                |   |                      |   |
| Instrument Panel         | ✓ |                      |   |
| Controls                 | ✓ | Infotainment Display | ✓ |

|                                                  |   |                    |   |
|--------------------------------------------------|---|--------------------|---|
| Music System                                     | ✓ | Camera             | ✓ |
| Lights                                           |   |                    |   |
| Headlight                                        | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights                          |   |                    |   |
| Right DRL: Low Brightness, Lamps Are Not Working | ! |                    |   |
| Air Conditioning                                 |   |                    |   |
| AC Cooling                                       | ✓ | AC System Leaks    | ✓ |
| Power/ Manual Windows                            | ✓ |                    |   |

### Interiors & Luggage

|                                |   |                |   |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner                      | ✓ | Toolkit        | ✓ |

### Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <35% | LHS Rear Tyre             | <35% |
| RHS Front Tyre             | <35% | RHS Rear Tyre             | <35% |
| Spare Tyre                 | <35% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE