



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 JAC JS4

INTELLIGENT | 48,046 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Apple play

Enjoy your drive with apple play

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	48046	 Specs	Yes
 Engine	1.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LJ12EKS39P4729481		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Parking Sensors Rear	
Reverse Camera		Front Camera	
Side Camera		Airbag Sides	
Airbag Driver Front		Airbag Passenger Front	
ABS			



Comfort & Convenience

Climate Control AC



Cruise Control



Power Window front -
Drivers Side



Power Window front -
Passenger Side



Power Windows Rear



Exteriors

Roof Rails



Running Lights



Rear Bumper Spoiler



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm 

Rear left door 

Rear right door

Panel: Scuffing > 50mm, Paint Chip-off > 5mm 

Fenders Condition

Left Fender

Condition: Scuffing 

Right Fender

Right Fender: Scuffing 

Quarter Panels Condition

Left Quarter Panel 

Right Quarter Panel
Condition: Light Scuffing 

Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm 

Hood Condition

Hood 

Running Board Condition

Left Running Board 

Right Running Board 

Sunroof Glass Condition (If Equipped)

Sun Roof Glass 

Windshield Condition

Front Windshield 

Rear Windshield 

Structural Assessment

Chassis Condition 

Apron 

Boot Floor 

Firewall Condition 

Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	!	Engine Performance	✓
Damage & Leaks: Mountings weak			
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys	
Master Key	✓
Dashboard	
Instrument Panel	✓

Controls	✓	Infotainment Display	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		
Air Conditioning			
AC Cooling	✓	Rear Left AC Vent	✓
Power/ Manual Windows	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Headliner	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<55%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE