

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2021 SUZUKI BALENO

GLX | 78,385 KM

Car highlights

Cruise control

Cruise control to drive with ease & comfort

Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	78385	Specs	Yes
Engine	1.4L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	HATCHBACK	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	4 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	MBHWB5B29MG620725		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		

Exteriors			
Fog Light Front	✓		

Safety & Security	
Parking Sensors Rear ✓	Reverse Camera ✓
Airbag Curtain Shield ✓	Airbag Driver Front ✓
Airbag Passenger Front ✓	ABS ✓
Entertainment	
Bluetooth Player ✓	

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door
Panel: Light Scuffing < 50mm, Paint Defect, Low Visibility Dent < 30mm

Rear left door

Rear right door
Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm

Fenders Condition

Left Fender
Condition: Light Scuffing

Right Fender

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Light Scuffing, Low Visual Dent

Rear Bumper Condition

Rear Bumper
Rear Bumper: Fully Repainted, Light Scuffing < 80mm

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm

Running Board Condition

Left Running Board

Right Running Board

Windshield Condition

Front Windshield
Condition: Driver Side/Stone Chip Mark<5mm

Rear Windshield

Structural Assessment

Chassis Condition

Apron

Boot Floor

Firewall Condition

Head Light Support Condition

Cowl Top

Cowl Top ✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Grill Condition

Light Scuffing < 50mm ⓘ

Panel Condition

Rear Trunk Panel ✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Shock Absorbers ✓

Electricals, Controls & Lights

Keys

Master Key ✓

Dashboard

Instrument Panel ✓

Controls	✓	Infotainment Display	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster	✓
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows Front Left: Power Window Noise/Vibration	!		

Interiors & Luggage

Dashboard And Instrument Panel Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted, Minor Scuffing/ Crack/ Fair Use Wear	!	Steering Wheel Steering Wheel Fair Use Wear	!
Headliner	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%
Spare Tyre	<15%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE