



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 LEXUS RX350

PRESTIGE | 36,513 KM

VIN: JTJCHCJA8S2020922

Car highlights



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort



Apple play

Enjoy your drive with apple play

Convenience Fee Applicable










Extra fee ranging from AED 2.5K-4K applicable



Amazing Comfort












Power driver seat, Memory Seats & more


























Basic Details

| | | | |
|--|--------------------------|---|----------------------------|
|  Kilometers | 36513 |  Specs | Yes |
|  Engine | 2.4L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | All Wheel Drive |
|  Body Type | SUV | Fuel Efficiency | 11.1 km/L mileage |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Grey |
|  Interior Trim | Leather Trim |  Number of Airbags | 7 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | JTJCHCJA8S2020922 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Safety & Security | | | |
|---|---|--------------------------|---|
| Adaptive cruise control |  | 360 degree Camera |  |
| Lane Departure Warning System |  | Navigation |  |
| Parking Sensors Front |  | Parking Sensors Rear |  |
| Auto Park Assist |  | Reverse Camera |  |
| Blind Spot Monitor |  | Collision Warning System |  |

| | | | |
|--|---|-----------------------------------|---|
| Front Camera |  | Side Camera |  |
| Airbag Sides |  | Airbag Curtain Shield |  |
| Airbag Knees |  | Airbag Driver Front |  |
| Airbag Passenger Front |  | ABS |  |
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Memory Seats |  | Power Window front - Drivers Side |  |
| Power Window front - Passenger Side |  | Ventilated Seat |  |
| Power Tailgate/ Power Trunk |  | Cool Box |  |
| Power Windows Rear |  | | |
|  Exteriors | | | |
| Fog Light Front |  | Roof Rails |  |
| Running Lights |  | Trailer Hook / Coupling |  |
|  Performance | | | |
| Paddle Shift |  | Hydraulic Suspensions |  |
| Hill Descent Control |  | | |
|  Entertainment | | | |
| Bluetooth Player |  | Apple Play |  |
| Android Auto Play |  | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Rim: Alloy Face Scuffing

Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Rim: Alloy Face Light Scuffing

Rim: Alloy Face/Light Scuffing

Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Steering, Suspension & Brakes

Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel



Controls



Infotainment Display



| | | | |
|-------------------------|---|-----------------------|---|
| Music System | ✓ | Camera | ✓ |
| Lights | | | |
| Headlight | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC System Leaks | ✓ |
| Rear Left AC Vent | ✓ | | |
| Rear Entertainment | ✓ | Power/ Manual Windows | ✓ |
| Memory Seats | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <90% | LHS Rear Tyre | <90% |
| RHS Front Tyre | <90% | RHS Rear Tyre | <90% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE