



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 NISSAN X TRAIL

SV | 99,505 KM

VIN: JN8AT3MM2PW001057

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play















Enjoy your drive with apple play



Amazing Comfort











Power driver seat























Basic Details

 Kilometers	99505	 Specs	Yes
 Engine	2.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	7 Seats	 Number of keys	1 Keys
 VIN number	JN8AT3MM2PW001057		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Lane Departure Warning System	
Navigation		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Collision Warning System	
Front Camera		Side Camera	

Airbag Sides		Airbag Curtain Shield	
Airbag Driver Front		Airbag Passenger Front	
ABS			
 Comfort & Convenience			
Climate Control AC		Cruise Control	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Tailgate/ Power Trunk		Power Windows Rear	
 Exteriors			
Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
 Performance			
Paddle Shift		Hill Descent Control	
 Entertainment			
Bluetooth Player		Apple Play	
Android Auto Play			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed




Exterior


Doors condition

Front right door

Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm 

Rear left door 

Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm 

Fenders Condition


Left Fender

Right Fender 

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel

Condition: Light Scuffing, Chip 

Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm 

Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping < 5mm 

Running Board Condition

Left Running Board

Right Running Board 

Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Windshield Condition

Front Windshield

Rear Windshield 

Structural Assessment

Chassis Condition

Apron 

Boot Floor

Head Light Support Condition 

Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Steering, Suspension & Brakes

Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel



Controls



Infotainment Display



Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Left AC Vent	✓		
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Headliner	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<55%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<55%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE