



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2021 KIA SELTOS**

**GT LINE | 134,595 KM**

VIN: MZBER8149MN179698

## **Car highlights**



### **Sunroof**

This car has a sunroof



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                    |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|--------------------|
|  Kilometers       | 134595            |  Specs             | Yes                |
|  Engine           | 1.6L              |  Option Type       | Fully Loaded       |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive  |
|  Body Type        | SUV               |  Fuel              | Petrol             |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Red |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags          |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys             |
|  VIN number     | MZBER8149MN179698 |                                                                                                     |                    |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Windows Rear                                                                                                   |  |                                     |                                                                                       |
|  <b>Exteriors</b>                 |                                                                                     |                                     |                                                                                       |
| Fog Light Front                                                                                                      |  | Roof Rails                          |  |

|                                                                                                                |   |                        |   |
|----------------------------------------------------------------------------------------------------------------|---|------------------------|---|
| Running Lights                                                                                                 | ✓ | Rear Bumper Spoiler    | ✓ |
|  <b>Safety &amp; Security</b> |   |                        |   |
| Parking Sensors Rear                                                                                           | ✓ | Reverse Camera         | ✓ |
| Airbag Sides                                                                                                   | ✓ | Airbag Curtain Shield  | ✓ |
| Airbag Driver Front                                                                                            | ✓ | Airbag Passenger Front | ✓ |
| ABS                                                                                                            | ✓ |                        |   |
|  <b>Entertainment</b>         |   |                        |   |
| Bluetooth Player                                                                                               | ✓ | Apple Play             | ✓ |
| Android Auto Play                                                                                              | ✓ |                        |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door

Panel: Low Visibility Dent < 30mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Light Scuffing



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood



### Roof Condition

Roof



### Running Board Condition

Left Running Board



Right Running Board



### Sunroof Glass Condition (If Equipped)

Sun Roof Glass



### Windshield Condition

Front Windshield

Condition: Air Bubbles, Driver Side/Stone

Chip Mark<5mm



Rear Windshield



### Structural Assessment

Chassis Condition



Apron



|                              |   |                       |   |
|------------------------------|---|-----------------------|---|
| Boot Floor                   | ✓ | Firewall Condition    | ✓ |
| Head Light Support Condition | ✓ |                       |   |
| Cowl Top                     |   |                       |   |
| Cowl Top                     | ✓ |                       |   |
| Rear View Mirror Condition   |   |                       |   |
| Left Hand Side Mirror        | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim             |   |                       |   |
| Left Front Alloy/ Rim        | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim       | ✓ | Right Rear Alloy/ Rim | ✓ |
| Monogram                     | ✓ |                       |   |
| Panel Condition              |   |                       |   |
| Rear Trunk Panel             | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

Keys

|                                                |   |                                                  |   |
|------------------------------------------------|---|--------------------------------------------------|---|
| Master Key                                     | ✓ |                                                  |   |
| Dashboard                                      |   |                                                  |   |
| Instrument Panel                               | ✓ |                                                  |   |
| Controls                                       | ✓ | Cruise Control                                   | ✓ |
| Infotainment Display                           | ✓ | Music System                                     | ✓ |
| Camera                                         | ✓ |                                                  |   |
| Lights                                         |   |                                                  |   |
| Headlight                                      |   |                                                  |   |
| Left: Scuff Marks > 50mm, Low Brightness lamps | ! | Interior Lights                                  | ✓ |
|                                                |   | Daylight Running Lights                          |   |
| Tail Light Cluster                             | ✓ | Right DRL: Low Brightness, Lamps Are Not Working | ! |
| Fog Lights                                     |   |                                                  |   |
| Left Fog Light: Condensation In Lamps          | ! |                                                  |   |
| Air Conditioning                               |   |                                                  |   |
| AC Cooling                                     | ✓ | AC System Leaks                                  | ✓ |
| Rear Blower Switch                             | ✓ |                                                  |   |
| Power/ Manual Windows                          | ✓ |                                                  |   |

## Interiors & Luggage

|                                                             |   |                                          |   |
|-------------------------------------------------------------|---|------------------------------------------|---|
| Dashboard And Instrument Panel                              |   | Central Console                          |   |
| Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted | ! | Box: Minor Crack/Fair Use Wear/ Scuffing | ! |
| Cup Holder                                                  | ✓ | Steering Wheel                           | ✓ |
| Sunvisor                                                    | ✓ | Seat Upholstery                          | ✓ |
| Manual Seat Movement                                        | ✓ | Seat Belts                               | ✓ |
| Head Rest                                                   | ✓ | Door Controls And Trim                   | ✓ |
| Carpet                                                      | ✓ | Headliner                                | ✓ |

Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre

<65%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE