



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2021 MAZDA 6**

**S | 98,679 KM**

VIN: JM7GL4S39M1453656

## Car highlights



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 98679             |  Specs             | Yes                  |
|  Engine           | 2.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 14.0 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number      | JM7GL4S39M1453656 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Windows Rear                                                                                                   |  |                                     |                                                                                       |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                     |                                                                                       |
| Parking Sensors Rear                                                                                                 |  | Reverse Camera                      |  |

|                                                                                                    |   |                        |   |
|----------------------------------------------------------------------------------------------------|---|------------------------|---|
| Airbag Sides                                                                                       | ✓ | Airbag Knees           | ✓ |
| Airbag Driver Front                                                                                | ✓ | Airbag Passenger Front | ✓ |
| ABS                                                                                                | ✓ |                        |   |
|  <b>Exteriors</b> |   |                        |   |
| Running Lights                                                                                     | ✓ |                        |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

#### Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off > 5mm 

#### Rear left door

Panel: Scuffing 

#### Rear right door

Panel: Light Scuffing < 50mm 

### Fenders Condition

#### Left Fender



#### Right Fender

Right Fender: Dent, Scuffing, Paint Chip-off 

### Quarter Panels Condition

#### Left Quarter Panel

Condition: Scuffing 

#### Right Quarter Panel

Condition: Light Scuffing 

### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Fully Repainted, Repaired, Scuffing > 80mm, Chip> 8mm, Paint Faded 

### Hood Condition

#### Hood



### Running Board Condition

#### Left Running Board



#### Right Running Board



### Windshield Condition

#### Front Windshield



#### Rear Windshield



### Structural Assessment

#### Chassis Condition



#### Apron



#### Boot Floor



#### Head Light Support Condition



#### Cowl Top

#### Cowl Top



|                        |   |                         |
|------------------------|---|-------------------------|
| Alloy Wheel/ Rim       |   |                         |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim ✓  |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim ✓ |
| Grill Condition        | ! |                         |
| Fully Repainted        |   |                         |
| Panel Condition        |   |                         |
| Rear Trunk Panel       | ✓ |                         |

## Engine & Transmission

|                                |   |                      |
|--------------------------------|---|----------------------|
| Engine                         |   |                      |
| Engine Body                    | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓     |
| Radiator Condition             | ✓ | Radiator Coolant ✓   |
| Transmission Operation         |   |                      |
| Gear Shifting                  | ✓ | Drive Axle ✓         |

## Steering, Suspension & Brakes

|                 |   |                         |
|-----------------|---|-------------------------|
| Brake System    |   |                         |
| Parking Brake   | ✓ | Brake Master Cylinder ✓ |
| Suspension      |   |                         |
| Shock Absorbers | ✓ |                         |

## Electricals, Controls & Lights

|                  |   |                        |
|------------------|---|------------------------|
| Keys             |   |                        |
| Master Key       | ✓ |                        |
| Dashboard        |   |                        |
| Instrument Panel | ✓ |                        |
| Controls         | ✓ | Infotainment Display ✓ |
| Music System     | ✓ | Camera ✓               |
| Lights           |   |                        |

|                           |   |                    |   |
|---------------------------|---|--------------------|---|
| Headlight                 | ! | Tail Light Cluster | ✓ |
| Right: Scuff Marks > 50mm |   |                    |   |
| Daylight Running Lights   | ✓ |                    |   |
| Air Conditioning          |   |                    |   |
| AC Cooling                | ✓ |                    |   |
| Power/ Manual Windows     | ✓ |                    |   |


**Interiors & Luggage**

|                                |   |                |   |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner                      | ✓ |                |   |


**Tyres**

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <35% | LHS Rear Tyre             | <35% |
| RHS Front Tyre             | <35% | RHS Rear Tyre             | <35% |
| Spare Tyre                 | <65% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE