



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 MG RX8**

**LUXURY | 27,541 KM**

VIN: LSJW84W96PG017322

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat, Ventilated Seats

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 27541             |  Specs             | Yes                  |
|  Engine           | 2.0L              |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 8 Airbags            |
|  Seating Capacity | 7 Seats           |  Number of keys    | 1 Keys               |
|  VIN number       | LSJW84W96PG017322 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                                      |  |                                                                                                |                                     |  |                                                                                                  |
|--------------------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------|-------------------------------------|--|--------------------------------------------------------------------------------------------------|
| <div> <b>Comfort &amp; Convenience</b></div>      |  |                                                                                                |                                     |  |                                                                                                  |
| Climate Control AC                                                                                                                   |  | <div></div> | Cruise Control                      |  | <div></div> |
| Power Window front - Drivers Side                                                                                                    |  | <div></div> | Power Window front - Passenger Side |  | <div></div> |
| Ventilated Seat                                                                                                                      |  | <div></div> | Power Tailgate/ Power Trunk         |  | <div></div> |
| Power Windows Rear                                                                                                                   |  | <div></div> |                                     |  |                                                                                                  |
| <div><div></div><div><b>Exteriors</b></div></div> |  |                                                                                                |                                     |  |                                                                                                  |

|                                                                                                                |   |                       |   |
|----------------------------------------------------------------------------------------------------------------|---|-----------------------|---|
| Fog Light Front                                                                                                | ✓ | Roof Rails            | ✓ |
| Running Lights                                                                                                 | ✓ |                       |   |
|  <b>Performance</b>           |   |                       |   |
| Paddle Shift                                                                                                   | ✓ | Hydraulic Suspensions | ✓ |
| Differential Locks                                                                                             | ✓ |                       |   |
|  <b>Safety &amp; Security</b> |   |                       |   |
| Parking Sensors Front                                                                                          | ✓ | Parking Sensors Rear  | ✓ |
| Reverse Camera                                                                                                 | ✓ | Airbag Sides          | ✓ |
| Airbag Curtain Shield                                                                                          | ✓ | Airbag Driver Front   | ✓ |
| Airbag Passenger Front                                                                                         | ✓ | ABS                   | ✓ |
|  <b>Entertainment</b>       |   |                       |   |
| Bluetooth Player                                                                                               | ✓ | Apple Play            | ✓ |
| Android Auto Play                                                                                              | ✓ |                       |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                                                       |                                                                                   |                |                                                                                     |
|-------------------------------------------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door<br>Panel: Low Visibility Dent < 30mm |  | Rear left door |  |
|-------------------------------------------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|

|                 |                                                                                   |
|-----------------|-----------------------------------------------------------------------------------|
| Rear right door |  |
|-----------------|-----------------------------------------------------------------------------------|

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                                   |                                                                                     |
|---------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm |  |
|---------------------------------------------------|-------------------------------------------------------------------------------------|

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Sunroof Glass Condition (If Equipped)

|                |                                                                                     |
|----------------|-------------------------------------------------------------------------------------|
| Sun Roof Glass |  |
|----------------|-------------------------------------------------------------------------------------|

### Windshield Condition

|                  |                                                                                     |                 |                                                                                       |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield |  | Rear Windshield |  |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                   |                                                                                     |            |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|------------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Boot Floor |  |
|-------------------|-------------------------------------------------------------------------------------|------------|---------------------------------------------------------------------------------------|

|                    |                                                                                     |                              |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|------------------------------|---------------------------------------------------------------------------------------|
| Firewall Condition |  | Head Light Support Condition |  |
|--------------------|-------------------------------------------------------------------------------------|------------------------------|---------------------------------------------------------------------------------------|

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Cowl Top               |   |                       |   |
| Cowl Top               | ✓ |                       |   |
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition        | ! |                       |   |
| Fully Repainted        |   |                       |   |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                       |   |                    |   |
|---------------------------------------|---|--------------------|---|
| Engine                                |   |                    |   |
| Engine Body                           | ! | Engine Performance | ✓ |
| Damage & Leaks: Timing cover repaired |   |                    |   |
| Engine Oil (Condition & Level)        | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger            | ✓ | Radiator Condition | ✓ |
| Radiator Coolant                      | ✓ |                    |   |
| Transmission Operation                |   |                    |   |
| Gear Shifting                         | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Steering        |   |                       |   |
| Steering wheel  | ✓ |                       |   |
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|            |   |
|------------|---|
| Keys       |   |
| Master Key | ✓ |

Dashboard

Instrument Panel



Controls



Infotainment Display



Music System



Camera



Lights

Headlight



Tail Light Cluster



Daylight Running Lights



Air Conditioning

AC Cooling



Power/ Manual Windows



Memory Seats



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Steering Wheel



Headliner



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre





## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE