



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 MG ZS

STD | 26,915 KM

VIN: LSJWS4U37SZ118298

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 26915             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 17.2 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number      | LSJWS4U37SZ118298 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                           |  |                                                                                     |                                                                                       |
|-----------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|  Exteriors             |  |                                                                                     |                                                                                       |
| Fog Light Front                                                                                           |  |  |  |
| Running Lights                                                                                            |  |  |  |
|  Comfort & Convenience |  |                                                                                     |                                                                                       |
| Cruise Control                                                                                            |  |  |  |
| Power Window front - Drivers Side                                                                         |  |  |  |
| Power Window front - Passenger Side                                                                       |  |  |  |
| Power Windows Rear                                                                                        |  |  |  |
|  Safety & Security     |  |                                                                                     |                                                                                       |

|                                                                                                        |   |                        |   |
|--------------------------------------------------------------------------------------------------------|---|------------------------|---|
| Parking Sensors Rear                                                                                   | ✓ | Reverse Camera         | ✓ |
| Airbag Driver Front                                                                                    | ✓ | Airbag Passenger Front | ✓ |
| ABS                                                                                                    | ✓ |                        |   |
|  <b>Entertainment</b> |   |                        |   |
| Bluetooth Player                                                                                       | ✓ | Apple Play             | ✓ |
| Android Auto Play                                                                                      | ✓ |                        |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

|                               |                                                                                     |                     |                                                                                       |
|-------------------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Doors condition               |                                                                                     |                     |                                                                                       |
| Front right door              |    | Rear left door      |    |
| Rear right door               |    |                     |                                                                                       |
| Panel: Low Visual Dent < 30mm |                                                                                     |                     |                                                                                       |
| Fenders Condition             |                                                                                     |                     |                                                                                       |
| Left Fender                   |    | Right Fender        |    |
| Quarter Panels Condition      |                                                                                     |                     |                                                                                       |
| Left Quarter Panel            |    | Right Quarter Panel |    |
| Rear Bumper Condition         |                                                                                     |                     |                                                                                       |
| Rear Bumper                   |  |                     |                                                                                       |
| Rear Bumper: Fully Repainted  |                                                                                     |                     |                                                                                       |
| Hood Condition                |                                                                                     |                     |                                                                                       |
| Hood                          |  |                     |                                                                                       |
| Running Board Condition       |                                                                                     |                     |                                                                                       |
| Left Running Board            |  | Right Running Board |  |
| Windshield Condition          |                                                                                     |                     |                                                                                       |
| Front Windshield              |  | Rear Windshield     |  |
| Structural Assessment         |                                                                                     |                     |                                                                                       |
| Chassis Condition             |  | Apron               |  |
| Boot Floor                    |  | Firewall Condition  |  |
| Head Light Support Condition  |  |                     |                                                                                       |
| Cowl Top                      |                                                                                     |                     |                                                                                       |
| Cowl Top                      |  |                     |                                                                                       |
| Alloy Wheel/ Rim              |                                                                                     |                     |                                                                                       |

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition        | ! |                       |   |
| Fully Repainted        |   |                       |   |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

 **Engine & Transmission**

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

 **Steering, Suspension & Brakes**

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

 **Electricals, Controls & Lights**

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |
| Music System     | ✓ | Camera               | ✓ |
| Lights           |   |                      |   |

|                         |   |                       |   |
|-------------------------|---|-----------------------|---|
| Headlight               | ✓ | Tail Light Cluster    | ✓ |
| Daylight Running Lights | ✓ |                       |   |
| Air Conditioning        |   |                       |   |
| AC Cooling              | ✓ | AC System Leaks       | ✓ |
| Rear Left AC Vent       | ✓ |                       |   |
| Rear Entertainment      | ✓ | Power/ Manual Windows | ✓ |

## Interiors & Luggage

|                                |   |                |   |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner                      | ✓ | Toolkit        | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <73% | LHS Rear Tyre             | <73% |
| RHS Front Tyre             | <73% | RHS Rear Tyre             | <73% |
| Spare Tyre                 | <73% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE