



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2025 JETOUR T2**

**LUXURY | 22,920 KM**

VIN: LVTDD24B2SD681849

## **Car highlights**



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort



### **Apple play**

Enjoy your drive with apple play

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Amazing Comfort**

Power driver seat, Ventilated Seats

Basic Details

|                                                                                                    |                      |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 22920                |  Specs             | Yes                  |
|  Engine           | 2.0L                 |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic            |  Drive             | All Wheel Drive      |
|  Body Type        | SUV                  |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels         |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Partial Leather Trim |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats              |  Number of keys    | 1 Keys               |
|  VIN number     | LVTDD24B2SD681849    |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                      |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------|---------------------------------------------------------------------------------------|
| <div> Safety &amp; Security</div> |                                                                                     |                      |                                                                                       |
| Adaptive cruise control                                                                                              |  | 360 degree Camera    |  |
| Lane Departure Warning System                                                                                        |  | Navigation           |  |
| Parking Sensors Front                                                                                                |  | Parking Sensors Rear |  |
| Reverse Camera                                                                                                       |  | Blind Spot Monitor   |  |
| Collision Warning System                                                                                             |  | Front Camera         |  |

|                                                                                                                    |   |                                     |   |
|--------------------------------------------------------------------------------------------------------------------|---|-------------------------------------|---|
| Side Camera                                                                                                        | ✓ | Airbag Sides                        | ✓ |
| Airbag Curtain Shield                                                                                              | ✓ | Airbag Driver Front                 | ✓ |
| Airbag Passenger Front                                                                                             | ✓ | ABS                                 | ✓ |
|  <b>Comfort &amp; Convenience</b> |   |                                     |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control                      | ✓ |
| Power Window front - Drivers Side                                                                                  | ✓ | Power Window front - Passenger Side | ✓ |
| Ventilated Seat                                                                                                    | ✓ | Power Windows Rear                  | ✓ |
|  <b>Exteriors</b>                 |   |                                     |   |
| Fog Light Front                                                                                                    | ✓ | Roof Rails                          | ✓ |
| Running Lights                                                                                                     | ✓ |                                     |   |
|  <b>Performance</b>             |   |                                     |   |
| Paddle Shift                                                                                                       | ✓ | Hill Descent Control                | ✓ |
|  <b>Entertainment</b>           |   |                                     |   |
| Bluetooth Player                                                                                                   | ✓ | Apple Play                          | ✓ |
| Android Auto Play                                                                                                  | ✓ |                                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

|                                           |                                                                                     |                                                  |                                                                                       |
|-------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------|---------------------------------------------------------------------------------------|
| Doors condition                           |                                                                                     |                                                  |                                                                                       |
| Front right door                          |    | Rear left door                                   |    |
| Rear right door                           |    |                                                  |                                                                                       |
| Panel: Low Visual Dent < 30mm             |                                                                                     |                                                  |                                                                                       |
| Fenders Condition                         |                                                                                     |                                                  |                                                                                       |
| Left Fender                               |    | Right Fender                                     |    |
| Quarter Panels Condition                  |                                                                                     |                                                  |                                                                                       |
| Left Quarter Panel                        |    | Right Quarter Panel<br>Condition: Light Scuffing |    |
| Rear Bumper Condition                     |                                                                                     |                                                  |                                                                                       |
| Rear Bumper                               |  |                                                  |                                                                                       |
| Rear Bumper: Fully Repainted, Dent < 50mm |                                                                                     |                                                  |                                                                                       |
| Hood Condition                            |                                                                                     |                                                  |                                                                                       |
| Hood                                      |  |                                                  |                                                                                       |
| Running Board Condition                   |                                                                                     |                                                  |                                                                                       |
| Left Running Board                        |  | Right Running Board                              |  |
| Sunroof Glass Condition (If Equipped)     |                                                                                     |                                                  |                                                                                       |
| Sun Roof Glass                            |  |                                                  |                                                                                       |
| Windshield Condition                      |                                                                                     |                                                  |                                                                                       |
| Front Windshield                          |  | Rear Windshield                                  |  |
| Structural Assessment                     |                                                                                     |                                                  |                                                                                       |
| Chassis Condition                         |  | Apron                                            |  |
| Boot Floor                                |  | Firewall Condition                               |  |
| Head Light Support Condition              |  |                                                  |                                                                                       |
| Cowl Top                                  |                                                                                     |                                                  |                                                                                       |

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Cowl Top               | ✓ |                       |   |
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |

|                         |   |                       |   |
|-------------------------|---|-----------------------|---|
| Music System            | ✓ | Camera                | ✓ |
| Lights                  |   |                       |   |
| Headlight               | ✓ | Tail Light Cluster    | ✓ |
| Daylight Running Lights | ✓ |                       |   |
| Air Conditioning        |   |                       |   |
| AC Cooling              | ✓ | AC System Leaks       | ✓ |
| Rear Left AC Vent       | ✓ |                       |   |
| Rear Entertainment      | ✓ | Power/ Manual Windows | ✓ |

### Interiors & Luggage

|                                |   |                |   |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner                      | ✓ | Toolkit        | ✓ |

### Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <73% | LHS Rear Tyre             | <73% |
| RHS Front Tyre             | <73% | RHS Rear Tyre             | <73% |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE