



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 NISSAN PATROL
SE TITANIUM | 31,083 KM

Car highlights



Power packed

Engine size of 4.0 Litres & 6.0 cylinders



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	31083	 Specs	Yes
 Engine	4.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	Fuel Efficiency	6.5 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	8 Seats	 Number of keys	1 Keys
 VIN number	JN8BY2NY9R9455373		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control		Lane Departure Warning System	
Navigation		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Collision Warning System	
Airbag Sides		Airbag Curtain Shield	

Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
 Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Tailgate/ Power Trunk	✓	Cool Box	✓
Power Windows Rear	✓		
 Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
Trailer Hook / Coupling	✓		
 Entertainment			
Rear Seat Entertainment	✓	Bluetooth Player	✓
Apple Play	✓	Android Auto Play	✓
 Performance			
Hill Descent Control	✓	Differential Locks	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door		Rear left door	
Panel: Light Scuffing < 50mm			

Rear right door	
Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	

Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing, Paint Chip-off			

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Fully Repainted, Light Scuffing < 80mm	

Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm	

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	---

Windshield Condition

Front Windshield		Rear Windshield	
Condition: Driver Side/Stone Chip Mark<5mm			

Structural Assessment

Chassis Condition		Apron	
-------------------	---	-------	---

Boot Floor		Firewall Condition	
------------	---	--------------------	---

Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel



Controls



Infotainment Display



Music System



Camera



Lights

Headlight



Tail Light Cluster



Daylight Running Lights



Air Conditioning

AC Cooling



AC System Leaks



Rear Left AC Vent



Rear Entertainment



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Steering Wheel



Headliner



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<75%

RHS Front Tyre

<55%

RHS Rear Tyre

<85%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE