



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 NISSAN ALTIMA**

**SV | 44,265 KM**

VIN: 1N4BL4A98NN378040

### **Car highlights**



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Music System**

Enjoy your drive with music system

#### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



#### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 44265             |  Specs             | Yes                  |
|  Engine           | 2.5L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 11.9 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number     | 1N4BL4A98NN378040 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |  |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |  |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  |  | Power Window front - Passenger Side |  |
| Power Windows Rear                                                                                                   |  |  |                                     |                                                                                       |
|  <b>Exteriors</b>                 |  |                                                                                     |                                     |                                                                                       |
| Fog Light Front                                                                                                      |  |  |                                     |                                                                                       |



## Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Blind Spot Monitor



Airbag Driver Front



Airbag Passenger Front



ABS



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door

Panel: Light Scuffing < 50mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Low Visual Dent



### Rear Bumper Condition

Rear Bumper



### Hood Condition

Hood



### Roof Condition

Roof



### Running Board Condition

Left Running Board



Right Running Board



### Sunroof Glass Condition (If Equipped)

Sun Roof Glass



### Windshield Condition

Front Windshield



Rear Windshield



### Structural Assessment

Chassis Condition



Apron



|                              |   |                       |   |
|------------------------------|---|-----------------------|---|
| Boot Floor                   | ✓ | Firewall Condition    | ✓ |
| Head Light Support Condition | ✓ |                       |   |
| Cowl Top                     |   |                       |   |
| Cowl Top                     | ✓ |                       |   |
| Alloy Wheel/ Rim             |   |                       |   |
| Left Front Alloy/ Rim        | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim       | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition              |   |                       |   |
| Light Scuffing < 50mm        | ! |                       |   |
| Panel Condition              |   |                       |   |
| Rear Trunk Panel             | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Steering        |   |                       |   |
| Steering wheel  | ✓ |                       |   |
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

Keys

|                         |   |                       |   |
|-------------------------|---|-----------------------|---|
| Master Key              | ✓ |                       |   |
| Dashboard               |   |                       |   |
| Instrument Panel        | ✓ |                       |   |
| Controls                | ✓ | Infotainment Display  | ✓ |
| Music System            | ✓ | Camera                | ✓ |
| Lights                  |   |                       |   |
| Headlight               | ✓ | Tail Light Cluster    | ✓ |
| Daylight Running Lights | ✓ |                       |   |
| Air Conditioning        |   |                       |   |
| AC Cooling              | ✓ | AC System Leaks       | ✓ |
| Rear Left AC Vent       | ✓ |                       |   |
| Rear Entertainment      | ✓ | Power/ Manual Windows | ✓ |



## Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel                 | ✓ | Headliner       | ✓ |
| Toolkit                        | ✓ |                 |   |



## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <35% | LHS Rear Tyre             | <35% |
| RHS Front Tyre             | <35% | RHS Rear Tyre             | <35% |
| Spare Tyre                 | <35% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE