



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 TOYOTA FORTUNER

VXR | 12,363 KM

VIN: MHFBU8FS9S0040993

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Apple play

Enjoy your drive with apple play

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Amazing Comfort

Power driver seat, Ventilated Seats

Basic Details

 Kilometers	12363	 Specs	Yes
 Engine	4.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	Fuel Efficiency	8.75 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	7 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MHFBU8FS9S0040993		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Airbag Sides	
Airbag Curtain Shield		Airbag Knees	
Airbag Driver Front		Airbag Passenger Front	

ABS	✓		
 Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Ventilated Seat	✓	Power Tailgate/ Power Trunk	✓
Power Windows Rear	✓		
 Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓		
 Performance			
Paddle Shift	✓	Differential Locks	✓
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓

Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Left AC Vent	✓		
Rear Entertainment	✓	Power/ Manual Windows	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Headliner	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%
Spare Tyre	<90%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE