



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2024 NISSAN KICKS

SV | 52,306 KM

VIN: 3N1CP5C95RL555027

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Android Auto

Enjoy your drive with Android Auto

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	52306	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	Fuel Efficiency	16.7 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	3N1CP5C95RL555027		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors				
Fog Light Front			Roof Rails	
 Comfort & Convenience				
Cruise Control			Power Window front - Drivers Side	
Power Window front - Passenger Side			Power Windows Rear	
 Safety & Security				

Parking Sensors Rear 	Reverse Camera 
Airbag Driver Front 	Airbag Passenger Front 
ABS 	
 Entertainment	
Bluetooth Player 	Android Auto Play 

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

 Exterior

Doors condition

Front right door

Panel: Paint Defect



Rear left door



Rear right door

Panel: Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Light Scuffing



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Low Visual Dent



Rear Bumper Condition

Rear Bumper

Rear Bumper: Scuffing > 80mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield

Condition: Front Wiper blades need replacement



Rear Windshield

Wiper blade damaged



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition			
Fully Repainted	!	Monogram	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Electricals, Controls & Lights

Keys			
Master Key			
Fair Use Wear	!		
Dashboard			

Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	!
		Condition: Knob Fair Use Wear	
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows	✓		



Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Gear Shift Knob: Knob Fair Use Wear	!
Steering Wheel			
Color Faded	!	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Carpet	
		Front Left Floor Mat: Smudge/Burn/Crack	!
Headliner	✓	Rear View Mirror	
		Damaged Mirror Casing	!
Toolkit	✓		



Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓

Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE