



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2021 NISSAN PATROL**

**SE TITANIUM | 91,226 KM**

VIN: JN8BY2NY2M9351199

## **Car highlights**



### **Power packed**

Engine size of 4.0 Litres & 6.0 cylinders



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 91226             |  Specs             | Yes                 |
|  Engine           | 4.0L              |  Option Type       | Semi Loaded         |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive    |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 6.5 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Blue |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags           |
|  Seating Capacity | 7 Seats           |  Number of keys    | 1 Keys              |
|  VIN number      | JN8BY2NY2M9351199 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                       |                                                                                     |                               |                                                                                       |
|-------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------|---------------------------------------------------------------------------------------|
|  Safety & Security |                                                                                     |                               |                                                                                       |
| Adaptive cruise control                                                                               |  | Lane Departure Warning System |  |
| Navigation                                                                                            |  | Parking Sensors Front         |  |
| Parking Sensors Rear                                                                                  |  | Reverse Camera                |  |
| Blind Spot Monitor                                                                                    |  | Collision Warning System      |  |
| Airbag Sides                                                                                          |  | Airbag Curtain Shield         |  |

|                                                                                                                    |   |                                     |   |
|--------------------------------------------------------------------------------------------------------------------|---|-------------------------------------|---|
| Airbag Driver Front                                                                                                | ✓ | Airbag Passenger Front              | ✓ |
| ABS                                                                                                                | ✓ |                                     |   |
|  <b>Comfort &amp; Convenience</b> |   |                                     |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control                      | ✓ |
| Power Window front - Drivers Side                                                                                  | ✓ | Power Window front - Passenger Side | ✓ |
| Power Tailgate/ Power Trunk                                                                                        | ✓ | Power Windows Rear                  | ✓ |
|  <b>Exteriors</b>                 |   |                                     |   |
| Fog Light Front                                                                                                    | ✓ | Roof Rails                          | ✓ |
| Running Lights                                                                                                     | ✓ | Rear Bumper Spoiler                 | ✓ |
| Trailer Hook / Coupling                                                                                            | ✓ |                                     |   |
|  <b>Entertainment</b>           |   |                                     |   |
| Rear Seat Entertainment                                                                                            | ✓ |                                     |   |
|  <b>Performance</b>             |   |                                     |   |
| Hydraulic Suspensions                                                                                              | ✓ | Hill Descent Control                | ✓ |
| Differential Locks                                                                                                 | ✓ |                                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

#### Front right door

Panel: Light Scuffing < 50mm, Low Visibility  
Dent < 30mm 

#### Rear left door

Panel: Scuffing, Dent 

#### Rear right door

Panel: Low Visual Dent < 30mm, Scuffing > 50mm 

### Fenders Condition

#### Left Fender

Condition: Scuffing, Dent 

#### Right Fender

Right Fender: Scuffing, Dent 

### Quarter Panels Condition

#### Left Quarter Panel

Condition: Scuffing 

#### Right Quarter Panel

Condition: Scuffing/ Scratch, Low Visual Dent 

### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Scuffing > 80mm, Fully Repainted 

### Hood Condition

#### Hood



### Running Board Condition

#### Left Running Board



#### Right Running Board



### Sunroof Glass Condition (If Equipped)

#### Sun Roof Glass



### Windshield Condition

#### Front Windshield



#### Rear Windshield



### Structural Assessment

#### Chassis Condition



#### Boot Floor



|                        |   |                              |   |
|------------------------|---|------------------------------|---|
| Firewall Condition     | ✓ | Head Light Support Condition | ✓ |
| Cowl Top               |   |                              |   |
| Cowl Top               | ✓ |                              |   |
| Alloy Wheel/ Rim       |   |                              |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Panel Condition        |   |                              |   |
| Rear Trunk Panel       | ✓ |                              |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| 4*4 Condition (If Applicable)  | ✓ |                    |   |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Steering        |   |                       |   |
| Steering wheel  | ✓ |                       |   |
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|            |   |
|------------|---|
| Keys       |   |
| Master Key | ✓ |
| Dashboard  |   |

|                         |   |                      |   |
|-------------------------|---|----------------------|---|
| Instrument Panel        | ✓ |                      |   |
| Controls                | ✓ | Infotainment Display | ✓ |
| Music System            | ✓ | Camera               | ✓ |
| Lights                  |   |                      |   |
| Headlight               | ✓ | Tail Light Cluster   | ✓ |
| Daylight Running Lights | ✓ |                      |   |
| Air Conditioning        |   |                      |   |
| AC Cooling              | ✓ |                      |   |
| Power/ Manual Windows   | ✓ |                      |   |

### Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel                 | ✓ | Headliner       | ✓ |

### Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <55% | LHS Rear Tyre             | <55% |
| RHS Front Tyre             | <55% | RHS Rear Tyre             | <55% |
| Spare Tyre                 | <15% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE